Site Ref HLAA/098/001

Site Address Land at Village Farm, Hope under Dinmore Information Source Call for sites

Site Area (ha) 2.27 Potential Housing <sub>N/A</sub> Capacity	Greenfield Brownfield	Agricultural Land Classification <sup>2</sup>
Is the site suitable for development?	Is development achievable on the site	Is the site available? ?
Yes 🗆	Yes 🗌	Yes 🔽
No 🗹	No 🖌	No 🗆
Part 🗆	Part	Don't Know
Possible timescale for develo	pment?	
1-5 Years	11-15 Years	Not In Current Plan Period
6-10 Years	16-20 Years	

# **Flood information**

Zone 3 (part of the site including the access)- Exception test would be required

#### Water information

Water Supply – DCWW Water only

### **Biodiversity information**

SSSI Zone of Impact. Consultation with Natural England is necessary and screening may be required. No protected species or statutory habitats recorded at this location.

#### **Highways information**

Comments: Access satisfactory but unknown how this would be affected by any flood alleviation scheme.

Conclusion: There are some issues with this site.

Site Address Land at Village Farm, Hope under Dinmore Information Source Call for sites

#### Landscape and Historic Environment information

Landscape Sensitivity: Moderate Landscape Capacity: Moderate - Low

Sensitivity & Capacity Analysis: The landscape is of moderate condition locally, but the area South of the site is of higher sensitivity and forms the sites' context. The site is not highly visible, but in open countryside and there is potential for local adverse effects. Constraints to development include the proximity of a watercourse and vegetation. SSSI in vicinity.

# Site probability

No potential

# Justification

Access to the site lies in floodzone 3, therefore the exception test is required.

Site Address	Land adjacent to Cherrybrook Clo	•	• •	Information	<b>Source</b> Cal	I for sites
Site Area (ha	<b>)</b> 6.32		Greenfield	✓	Agricultural	Land
Potential Ho Capacity	using <sub>N/A</sub>		Brownfield		Classificatio	
Is the site sui for developm		ls develo achieval	opment ble on the si	te?	Is the site	available?
Yes 🗌		Yes	]		Yes	
No 🔽		No 🔽			No	
Part		Part	]		Don't Knov	w 🗆
Possible time	scale for develo	pment?				
1-5 Years		11-15 Years		Not In Curre	nt Plan Perio	d 🔽
6-10 Years		16-20 Years				

Site Ref HLAA/194/001

Post Code HR6 0PJ

# **Flood information**

Zone 3 (1/3 of site approx)- Exception test would be required

#### Water information

Water Supply – DCWW Water only

Settlement Name Hope under Dinmore

### **Biodiversity information**

SSSI Zone of Impact. Consultation with Natural England is necessary and screening may be required. No protected species or statutory habitats recorded at this location.

#### Highways information

Comments: Access to A49 would not be acceptable

Possible mitigation: Access via HLAA/434/001 would be subject to third party land agreement

Conclusion: There are major issues with this site.

Site Ref HLAA/194/001

Site Address Land adjacent to filling station, opposite Cherrybrook Close, Hope under Dinmore

Information Source Call for sites

#### Landscape and Historic Environment information

Landscape Sensitivity: Moderate Landscape Capacity: Moderate

Sensitivity & Capacity Analysis: The landscape is of a moderate condition locally. The site has a limited visual envelope - some residential receptors, and only localised key views from the main roads are affected. If the location is sustainable, the site has capacity for large-scale development in landscape terms, subject to constraints PRoW site boundary to the north, railway line.

# Site probability

No potential

#### Justification

There is a watercourse running along the south east area of the site with the eastern portion of the site at risk of flood zone 3 therefore the exception test is required. The eastern boundary of the site is where site access is more suitable. There are major issues with direct access onto the A49 therefore access via HLAA/434/001 may be required which is third party land. With access difficulties and flood risk the site is not a suitable location for development

Site Ref HLAA/434/001

Site Address Hope under Dinmore

Information Source Call for sites

Site Area (ha) 0.47 Potential Housing <sub>N/A</sub> Capacity	Greenfield Brownfield	Agricultural Land Classification 2
Is the site suitable for development?	Is development achievable on the site	Is the site available? ?
Yes 🗌	Yes 🗌	Yes 🔽
No 🔽	No 🔽	No 🗆
Part	Part	Don't Know
Possible timescale for develo	pment?	
1-5 Years	11-15 Years	Not In Current Plan Period
6-10 Years 🛛	16-20 Years	

# **Flood information**

Zone 3 (along watercourse through site) & Zone 2 (majority of site)- Exception test would be required

# Water information

Water Supply – DCWW Water only

# **Biodiversity information**

SSSI Zone of Impact. Consultation with Natural England is necessary and screening may be required. No protected species or statutory habitats recorded at this location.

### **Highways information**

Comments: Access satisfactory but low lying land.

Conclusion: There are some issues with this site.

Site Address Hope under Dinmore

#### Landscape and Historic Environment information

Landscape Sensitivity: Moderate Landscape Capacity: Moderate - High

Sensitivity & Capacity Analysis: The landscape is of moderate condition locally. Development would entail crossing the watercourse. The site has a very limited visual envelope. There is potential for development subject to constraints- railway and watercourse which is a tributary of Special Area of Conservation and a Site of Special Scientific Interest with the River Lugg. Boundary vegetation should be retained and/or improved.

# Site probability

No potential

#### Justification

Watercourse crossing site which is a potential high risk flood zone 3 area. This limits the potential scope for development on the site given its linear shape.

# Settlement Name Hope under Dinmore

0.25

Site Area (ha)

Site Address Land to west of Church Hill Coppice

Potential Housing <sub>N/A</sub> Capacity	Brownfield	Agricultural Land Classification <sup>2</sup>
Is the site suitable for development?	Is development achievable on the site	Is the site available? ?
Yes 🗆	Yes 🗌	Yes 🗆
No 🗹	No 🔽	No 🗆
Part 🗌	Part	Don't Know 🗹
Possible timescale for deve	elopment?	
1-5 Years	11-15 Years	Not In Current Plan Period
6-10 Years	16-20 Years	

Greenfield

✓

# **Flood information**

Zone 3 (majority of site)- Exception test would be required

# Water information

Water Supply – DCWW Water only

# **Biodiversity information**

SSSI Zone of Impact. Consultation with Natural England is necessary and screening may be required. No protected species or statutory habitats recorded at this location.

# **Highways information**

Comments: Slight visibility issues. Large ditch.

Possible mitigation: Access via 098/001

Conclusion: There are some issues with this site.

Site Ref O/Hudin/001

Information Source LA officer identified

**Site Address** Land to west of Church Hill Coppice

Information Source LA officer identified

#### Landscape and Historic Environment information

Landscape Sensitivity: Moderate Landscape Capacity: Moderate - High

Sensitivity & Capacity Analysis: The landscape is of moderate condition locally. The village has some limited capacity for expansion here. The site has a very limited visual envelope, but is on the road frontage. The site has capacity for development, subject to constraints - Public Right of Way at Northern site boundary, railway and watercourse.

# Site probability

No potential

# Justification

The majority of the site is in flood zone 3. Development in this location would be unsuitable due to flooding constraints.

Site Ref TDAC

Site Address Hope-under-Dinmore Primary School

Information Source Public sector land

Site Area (ha) 0.40 Potential Housing <sub>N/A</sub> Capacity	Greenfield Brownfield	<ul> <li>Agricultural Land</li> <li>Classification</li> </ul>
Is the site suitable for development?	Is development achievable on the site	Is the site available? e?
Yes 🗆	Yes 🗌	Yes
No 🔽	No 🔽	No
Part	Part	Don't Know
Possible timescale for develo	pment?	
1-5 Years	11-15 Years	Not In Current Plan Period 🛛 🗹
6-10 Years 🛛	16-20 Years	

# **Flood information**

Zone 1 - Development is appropriate. A flood risk assessment will be required for sites greater than 1 Ha. Nearby ordinary watercourses and other sources of flooding such as surface water flooding should be explored for potential flood risk.

# Water information

Water Supply – DCWW Water only

### **Biodiversity information**

SSSI Zone of Impact. Special Wildlife Site- adjacent to Southern boundary of site. UK BAP Priority Habitat (Habitat of Principal Importance)- Deciduous Woodland on site.

### Highways information

Comments: Access to and from A49 is difficult.

Conclusion: There are major issues with this site.

Site Address Hope-under-Dinmore Primary School

Information Source Public sector land

#### Landscape and Historic Environment information

Landscape Sensitivity: Moderate - Low Landscape Capacity: Moderate - High

Sensitivity & Capacity Analysis: The landscape is of a moderate condition locally. The site is not highly visible but development would have potential effects on the setting of the Grade II\* listed church. There is potential for a small scale, sensitive development. Boundary vegetation should be protected, retained and improved.

# Site probability

No potential

# Justification

Due to difficulties with access this site is not deemed to have potential within the SHLAA to yield a minimum of 5 dwellings. Site has planning permission for 1 dwelling (132001).

