Bishopstone Group Neighbourhood Plan

Site Assessment

Brought forward in questionnaire and call for sites in April 2014.

January 2019



Map produced by MAGIC on 9 December, 2018.

(c) Crown Copyright and database rights 2018. Ordnance Survey 100022861.

Copyright resides with the data suppliers and the map must not be reproduced without their permission. Some information in MAGIC is a snapshot of the information that is being maintained or continually updated by the originating organisation. Please refer to the metadata for details as information may be illustrative or representative rather than definitive at this stage.

Bishopstone Village Site Options Map

Scale 1:6,000

At A4 size

NORTH

	Bishopstone Site Assessment – Site 1
Site information	
Site name	Site 1 – Bishon Lane
Address	Bishon Lane HR4 7HY
Current use	Meadow land used for grazing
Gross are (Ha)	0.89 ha
SHLAA ref if	n/a
applicable	
Method of site	Brought forward in answer to a questionnaire request for sites in
identification	April 2014 (site suggested in one questionnaire response)
Type of site	Greenfield
Planning history	None
Site character	Site lies on outskirts of Bishopstone village. Mainly sloping,
	steep in parts, with mature hedgerows
Access	Access available from C1097 via U90016 Bishon Lane, a single
	track road terminating at Bishon Common. No footway or street
	lighting.
Technical	
assessment	
Ecology	High sensitivity. Traditional hay meadow - potential for harm to
	meadow flora and insects. Site falls within Special Protection
	Area for Birds. SSSI at Bishon Common 200 metres distant
Landscape	High sensitivity. Site is in open countryside in a prominent
	position on the side of a ridge with extensive views NE over
	Yazor Brook valley and Bishon Common SSSI. towards Grade II*
	listed Foxley parkland
Agriculture	Grade 2/3 agricultural land
Heritage	n/a
Flood risk	Site is in low risk flood zone and not in flood zone 2/3
Water supply/	Mains sewer runs down meadow to the east of Bishon Lane
Waste water	Available headroom at present at Eign water treatment works
treatment	depending on size of development. Residents further down
	Bishon Lane have experienced flooding with raw sewage when
	the main sewer pumping station on Bishon Common has failed
	to cope. Water supply runs down meadow east of Bishon Lane
Highways	Site lies on single track lane terminating at Bishon Common.
	Lane is also a PROW used by walkers to access SSSI at Bishon
	Common
Community	Shop, surgery and mobile post office at Credenhill 2 miles
facilities and	distant by road. Limited bus service (4 buses a day, not Sundays)
services	to Hereford runs along C1097; half-hourly bus service runs from

Credenhill to Hereford. Small community centre at Bridge
Sollars church one mile distant by road.
SSSI at Bishon Common 200 metres distant
Poor access, possibility of ecological damage, SSS1 within 200
metres.
Landscape sensitivity
No
n/a
Unlikely – landowner has not offered site
n/a
Unlikely – landowner has not offered site
Site not recommended for allocation in NDP due to major
constraints and lack of support by landowner

	Bishopstone Site Assessment - Site 2
Site information	
Site name	Site 2 - Bishopstone Court
Address	Bishopstone HR4 7JQ
Current use	Traditional grass meadowland used for grazing.
Gross are (Ha)	0.32 ha
SHLAA ref if	n/a
applicable	
Method of site	Brought forward in answer to a questionnaire request for sites in
identification	April 2014 (site suggested in one questionnaire response).
Type of site	Greenfield
Planning history	None
Site character	Site lies detached from main settlement of Bishopstone one mile
	distance by road, close to Bishopstone Court and church and near
	site of deserted mediaeval village. Flat site adjacent to farm
	buildings. Site is classified as open countryside under
	Herefordshire Core Strategy
Access	Access available from C1098 single track road via U90014, a
	single track road terminating at Northern boundary of site. No
	footway or street lighting
Technical	
assessment	
Ecology	Medium sensitivity – potential for harm to traditional
	meadowland flowers and insects
Landscape	Medium sensitivity due to possible impact on historic landscape
Agriculture	Grade 2/3 agricultural land
Heritage	High Sensitivity. Site in close proximity to Bishopstone Court
	(Grade II listed house, bridge and moat), Bishopstone church
	(Grade II listed) and site of deserted mediaeval village.
Flood risk	Site is in low risk flood zone and not in flood zone 2/3
Water supply/	Water supply – private supply from spring and tank on
Waste water	Bishopstone Hill; no access to sewer
treatment	
Highways	Direct access to U90014
Community	Shop, surgery and mobile post office at Credenhill 3 miles distant
facilities and	by road. Limited bus service runs through Bishopstone village.
services	Small community centre at Bridge Sollars church one mile distant
	by road
Other protection	

Deliverability

Minor constraints to	
site	
Major constraints to site	Poor access. Proximity to heritage sites.
Significant constraints	Lack of conformity to Core Strategy
Is site suitable to allocate	No
Is development achievable	n/a
Is site available in Plan period 0-5 years 6-10 years 11-15 years	n/a
15+ years Potential housing development capacity	n/a
Additional information	
Summary	
Probability of site coming forward	n/a
Justification of site coming forward	Site not recommended for allocation in NDP due to major and significant constraints and lack of support by landowner

	Bishopstone Site Assessment - Site 3
Site	
information	
Site name	Site 3 Opposite Bishopstone Lodge
Address	Village Road, Bishopstone HR4 7JE
Current use	Waste ground, rough grass
Gross are (Ha)	0.05 ha
SHLAA ref if	n/a
applicable	
Method of site	Brought forward in answer to a questionnaire request for sites in
identification	April 2014, site suggested in one questionnaire response
Type of site	Greenfield (waste)
Planning	Planning application for erection of single storey dwelling and
history	single garage refused March 2007.
Site character	Site lies on C1097 at west end of Bishopstone village
Access	Access directly on to C1097. No street lighting or footway but 30
	mph speed limit on C1097
Technical	
assessment	
Ecology	n/a
Landscape	n/a
Agriculture	Grade 2/3 agricultural land
Heritage	Low sensitivity. Site of Roman road runs at N edge of site alongside
0	C1097
Flood risk	Site is in low risk flood zone and not in flood zone 2/3
Water supply/	Mains water and sewer on C1097 adjacent to site
Waste water	
treatment	
Highways	Access immediately onto C1097
Community	Shop, surgery and mobile post office at Credenhill 2 miles distant by
facilities and	road. Limited bus service to Hereford runs along C1097; half-hourly
services	bus service available from Credenhill to Hereford. Small community
	centre at Bridge Sollars church one mile distant by road.
Other	n/a
protection	
Deliverability	
Minor	Heritage - site borders on Roman road
constraints to	
site	
Major	n/a
constraints to	

site	
Significant	n/a
constraints to	
site	
Is site suitable	Yes
to allocate	
Is	Yes
development	
achievable	
Is site	
available in	
Plan period	
0-5 years	Yes
6-10 years	
11-15 years	
15+ years	
Potential	1
housing	
development	
capacity	
Additional	The owner of the site has recently died and probate is still going
information	through.
Summary	
Probability of	In the light of the previous application for planning permission we
site coming	believe that a further application is likely once probate has been
forward	completed.
Justification of	Site is recommended to be allocated in the NDP as it is within the
site coming	Bishopstone settlement area and is covered by NDP Policy H1.7
forward	

Bishopstone Site	Bishopstone Site Assessment - Site 4
assessment	
Site information	
Site name	Site 4 - Bishopstone House
Address	Village road HR4 7JG
Current use	Pasture/grazing
Gross are (Ha)	0.5 ha
SHLAA ref if	n/a
applicable	
Method of site	Brought forward in answer to a questionnaire request for sites in
identification	April 2014 (site suggested in one questionnaire response)
Type of site	Greenfield
Planning history	None
Site character	Site lies on outskirts of Bishopstone village. Flat site
Access	Access possible onto direct C1097. Drive to Bishopstone House
	runs along east side of site. C1097 becomes single track
	westward from junction with drive. No street lighting or
	footway but 30 mph speed limit on C1097
Technical	
assessment	
Ecology	Traditional pasture meadow - potential for harm to meadow
	flora and insects.
Landscape	n/a
Agriculture	Grade 2/3 agricultural land
Heritage	High sensitivity. Site is within 100m of Roman Villa site with
	tessellated pavement at Bishopstone House. Roman road runs
	on other side of C1097
Flood risk	Site is in low risk flood zone and not in flood zone 2/3; site is
	waterlogged with water running from it constantly during
	winter
Water supply/	Access available to mains and sewer in road C1097. Available
Waste water	headroom at present at Eign water treatment works depending
treatment	on size of development
Highways	Access onto C1097 which runs on S side of site
Community	Shop, surgery and mobile post office at Credenhill 2 miles
facilities and	distant by road. Limited bus service to Hereford runs along
services	C1097; half-hourly bus service available from Credenhill to
	Hereford. Small community centre at Bridge Sollars church one
-	mile distant by road.
Other protection	n/a
Deliverability	

Minor constraints	Potential harm to meadow flora and insects
to site	rotertali harri to meddow nord and moeelo
Major constraints	
to site	
Significant	High sensitivity for heritage – proximity to Roman villa site and
constraints to site	risk of damage to archaeology on site between villa and Roman
constraints to site	road
Is site suitable to	No
allocate	
Is development	n/a
achievable	
Is site available in	Unlikely – owner has not offered site
Plan period	
0-5 years	
6-10 years	
11-15 years	
15+ years	
Potential housing	n/a
development	
capacity	
Additional	
information	
Summary	
Probability of site	Unlikely – owner has not offered site
coming forward	
Justification of site	Site not recommended for allocation in NDP due to significant
coming forward	constraint and lack of support by landowner

Bishopstone Site	Bishopstone Site assessment - Site 5
assessment	
Site information	
Site name	Site 5 - Land south of C1097
Address	Village Road, Bishopstone HR4 7HX
Current use	Pasture/grazing for livestock
Gross are (Ha)	0.78 ha
SHLAA ref if	n/a
applicable	
Method of site	Brought forward in answer to a questionnaire request for sites in
identification	April 2014, site suggested in one questionnaire response
Type of site	Greenfield
Planning history	n/a
Site character	Site lies on C1097 in centre of Bishopstone village, on top of
	south facing ridge. Flat site with mature hedgerows.
Access	Access possible directly onto C1097, No street lighting or
	footway but 30 mph speed limit on C1097
Technical	
assessment	
Ecology	Moderate sensitivity. Ancient hedgerow on N side of site
	identified as possibly pre-Saxon
Landscape	High sensitivity. Site is in open countryside with extensive long-
-	distance views to S, SW and SE over the Wye valley to Hay
	Bluff.
Agriculture	Grade 2/3 agricultural land
Heritage	Low sensitivity. Site of Roman road runs along north edge of
	site.
Flood risk	Site is in low risk flood zone and not in flood zone 2/3
Water supply/	Access available to mains and sewer in road C1097. Available
Waste water	headroom at present at Eign water treatment works depending
treatment	on size of development
Highways	Access to C1097
Community	Shop, surgery and mobile post office at Credenhill 2 miles
facilities and	distant by road. Limited bus service to Hereford runs along
services	C1097; half-hourly bus service available from Credenhill to
	Hereford. Small community centre at Bridge Sollars church one
	mile distant by road.
Other protection	n/a
Deliverability	
Minor constraints	Low sensitivity for heritage
to site	- č

	Ma danata ann aitimiter (an anala an
Major constraints	Moderate sensitivity for ecology
to site	
Significant	High landscape sensitivity
constraints to site	
Is site suitable to	No
allocate	
Is development	n/a
achievable	
Is site available in	Unlikely – landowner has not offered site
Plan period	
0-5 years	
6-10 years	
11-15 years	
15+ years	
Potential housing	n/a
development	
capacity	
Additional	Site is in similar landscape position to Site 8 (HC Planning ref
information	0/Bishtn/001) for which the Planning officer report stated
	"Development of the site would adversely affect the
	villagescape and pattern, is uncharacteristic and inappropriate
	in this location."
Summary	
Probability of site	Unlikely – landowner has not offered site
coming forward	
Justification of site	Site not recommended for allocation in NDP due to constraints
coming forward	and lack of support by landowner

Bishopstone Site	Bishopstone Site Assessment - Site 6
assessment	
Site information	
Site name	Site 6 - Land Adjacent to Pleck Cottage
Address	Bishopstone HR4 7HX
Current use	Meadow land/grazing
Gross are (Ha)	0.67 ha
SHLAA ref if	HLAA/235/001
applicable	
Method of site	Offered by landowner following Call for Sites. Brought forward
identification	in answer to a questionnaire request for sites in April 2014 (site
	suggested in one questionnaire response)
Type of site	Greenfield
Planning history	None
Site character	Site lies within the settlement of Bishopstone. Flat site with
	mature hedgerows on South, North and East boundary.
Access	Site lies adjacent to Pleck Cottage (Grade II listed, derelict) and
	behind a row of 1960s bungalows. No direct access to site from
	C1097. Access from C1097 possible via back drive to Bishon
	Farm and across Pleck Cottage site. No street lighting or footway
	but 30 mph speed limit on C1097
Technical	
assessment	
Ecology	Traditional pasture meadow – has not been ploughed for at least
	last 70 years. May be potential for harm to meadow flora and
	insects.
Landscape	SHLAA report rated the site with High – Moderate Landscape
	sensitivity: village landscape very sensitive to change especially
	any that would result in loss of field and vegetation patterns
Agriculture	Grade 2/3 agricultural land
Heritage	Site is within 25 metres of Pleck Cottage (Grade II listed) and
80	within 135 metres of Bishon Farmhouse (Grade II listed)
Flood risk	Site is in low risk flood zone and not in flood zone 2/3. After
	heavy rain site floods with surface water and overspill
	sometimes floods two adjacent cottages.
Water supply/	Not on site. Sewer and mains water in road C1097. Available
Waste water	headroom at present at Eign water treatment works depending
treatment	on size of development
Highways	No direct access to site from C1097. Access from C1097 possible
- ingitting 5	via back drive to Bishon Farm and across Pleck Cottage site
Community	Shop, surgery and mobile post office at Credenhill 2 miles
Community	onop, surgery and mobile post onice at Credennin 2 nines

facilities and	distant by road. Limited bus service to Hereford runs along
services	C1097; half-hourly bus service available from Credenhill to
	Hereford. Small community centre at Bridge Sollars church one
	mile distant by road.
Other protection	SSSI at Bishon Common 400m N
Deliverability	
Minor constraints	
to site	
Major constraints	Landscape sensitivity, proximity to listed buildings, no direct
to site	access to site
Significant	Increased run-off from new buildings and road will cause
constraints to site	additional surface water flooding with consequent greater
	damage to neighbouring properties
Is site suitable to	Yes with provisos. As recommended in SHLAA a very low
allocate	density, sensitively designed development may be possible
	subject to access being achieved and successful measures taken
	to mitigate constraints
Is development	Yes subject to mitigation.
achievable	
Is site available in	
Plan period	
0-5 years	
6-10 years	
11-15 years	
15+ years	Yes
Potential housing	8-10
development	
capacity	
Additional	During NDP consultation respondents strongly opposed
information	development on this site and it was not included within the
	expanded settlement area.
Summary	
Probability of site	Landowner has offered site
coming forward	
Justification of	Site is recommended to be allocated for possible long-term
site coming	development subject to mitigation of constraints. This will
forward	necessitate a change to the settlement boundary.

	Bishopstone Site assessment - Site 7
Site information	
Site name	Site 7 - Bishon Farm
Address	Bishopstone HR4 7JE
Current use	Part pasture-orchard used for grazing, part farm house,
	redundant buildings and barns with hard-standing, two
	dilapidated Dutch barns on northern boundary.
Gross are (Ha)	2.4 hectares
SHLAA ref if	HLAA/235/002 (covers part of site only)
applicable	
Method of site	Part of site offered by landowner following Call for Sites. Site
identification	also brought forward in answer to a questionnaire request for
	sites in April 2014, (site suggested in 26 questionnaire responses)
Type of site	Part greenfield, part brownfield
Planning history	Planning permission granted 2006 for conversion of redundant
	farm buildings in rear of site into seven houses and bungalows.
	New access drive put in but conversion not carried out.
Site character	Site lies in centre of the settlement of Bishopstone adjoining
	C1097; flat site with mature hedgerows. Site includes part (18%)
	of a traditional orchard with only 2 mature trees remaining;
	Bishon Farmhouse (Grade II listed in poor condition) and 19th
	century farmyard with redundant barns; two dilapidated Dutch
	barns on northern boundary; part of 70 year old orchard on east
	of site between house and road with 13 trees remaining.
	Millennium Oak tree planted by villagers is within site at south
	east corner
Access	Access available onto C1091 to south of site and onto access drive
	through site. No street lighting or footway; 30 mph speed limit
	on C1097
Technical	
assessment	
Ecology	Site includes part of a traditional orchard in poor condition with
	only 2 mature trees now remaining within site area. Potential for
	protected species in hedgerow/orchard. Landowner has
	commissioned an Orchard Management Plan. Two ponds used
	for watering livestock lie just outside site to NW.
Landscape	Low/moderate sensibility. SHLAA report stated that the orchard,
	of which the site is part, formed an integral element of the village
	character and setting. This is now much diminished due to loss of
	mature trees.
Agriculture	Grade 2/3 agricultural land, good to moderate. Farmed

	traditionally for last 100 years with no use of chemicals
Heritage	Bishon Farm (Grade II listed) at north of site. Pleck Cottage
Tiemage	(Grade II listed) is adjacent 25 metres to east of site
Flood risk	Site is in a low risk flood zone, not in zone 2/3
Water supply/	Water main runs through site. Sewer in road C1097. Available
Waste water	headroom at present at Eign water treatment works depending
treatment	on size of development. This development would need own
	provision for sewage/waste water
Highways	Access available onto C1091 which runs south of site. Farm drive
0	runs north from C1097 through site.
Community	Shop, surgery and mobile post office at Credenhill 2 miles
facilities and	distant. Limited bus service to Hereford runs along C1097; half-
services	hourly bus service available from Credenhill to Hereford. Small
	community centre at Bridge Sollars church one mile distant
Other protection	SSSI at Bishon Common 500 metres North East
Deliverability	
Minor constraints	Ecology - potential for harm to remains of traditional orchard.
to site	Mitigation measures to alleviate impact on orchard are set out in
	an Orchard Management Plan commissioned by landowner.
	Development will protect remaining orchard trees which are
	currently neglected and at risk.
	Heritage - sensitive development can mitigate effect on Bishon
	farmhouse.
Major constraints	n/a
to site	
Significant	n/a
constraints	
to site	
Is site suitable to	Yes
allocate	
Is development	Yes
achievable	
Is site available	
in	
Plan period	Yes
0-5 years	
6-10 years	
11-15 years	
15+ years	
Potential housing	20
development	
capacity	

Additional	SHLAA said development not appropriate on the site due to
information	impact on traditional orchard but HC ecologist later reversed this
	opinion due to poor state of remaining trees, and supported
	proposed development. Development will protect remaining
	orchard trees and include community space requested by
	residents during consultation.
	Residents support development as it will provide a "centre" to
	the village. Development will include a community space for
	villagers.
Summary	
Probability of site	Likely in plan period. Owner has offered part of site
coming forward	
Justification of	Recommended to be allocated in NDP due to suitability of site,
site coming	location and access, low landscape impact, and support from
forward	residents.

	Bishopstone Site assessment Site 8
Site information	
Site name	Site 8 Land to rear of almshouses
Address	Village road, Bishopstone HR4 7JE
Current use	Tillage (growing crops)
Gross are (Ha)	0.69 ha
SHLAA ref if	0/Bishtn/001
applicable	
Method of site	LA officer identified
identification	
Type of site	Greenfield
Planning history	None
Site character	Flat site behind almshouses extending to west behind row of 1960s bungalows
Access	Access possible from C1097 via bridleway BN5. No street
	lighting or footway but 30 mph speed limit on C1097
Technical	
assessment	
Ecology	n/a
Landscape	High sensitivity noted by HC Planning Officer "Site is in open
	countryside, in a prominent location on a ridge with extensive
	long-distance views to South West, South and South east over
	the Wye Valley to Hay Bluff. Development would adversely
	affect villagescape and pattern is uncharacteristic and
	inappropriate in this location (SHLAA)
Agriculture	Grade 2/3 agricultural land
Heritage	n/a
Flood risk	Site is in low risk flood zone and not in flood zone 2/3
Water supply/	Access available to mains and sewer in road C1097. Available
Waste water	headroom at present at Eign water treatment works depending
treatment	on size of development
Highways	C1097 runs on S of site, bridleway BN 5 on E.
Community	Shop, surgery and mobile post office at Credenhill 2 miles
facilities and	distant. Limited bus service (4 buses a day, not Sundays) to
services	Hereford runs along C1097; half-hourly bus service runs from
	Credenhill to Hereford. Small community centre at Bridge
	Sollars church one mile distant
Other protection	n/a
Deliverability	
Minor constraints	
to site	

Major constraints	
to site	
Significant	High landscape sensitivity identified in SHLAA
constraints to site	Thigh landscape sensitivity identified in STILAA
Is site suitable to	No
	NO
allocate	
Is development	n/a
achievable	
Is site available in	Unlikely – landowner has not offered site
Plan period	
0-5 years	
6-10 years	
11-15 years	
15+ years	
Potential housing	n/a
development	
capacity	
Additional	
information	
Summary	
Probability of site	Unlikely – landowner has not offered site
coming forward	
Justification of	Site not recommended for allocation in NDP due to significant
site coming	constraints and lack of support by landowner. Site identified by
forward	SHLAA as unacceptable due to prominence within village and
	potential impact on villagescape.
	I I I I I I I I I I I I I I I I I I I

Bishopstone Group NDP Sites Assessment – Summary

Of the eight sites which came forward only two (sites 6 and 7) were offered by the landowner. Sites 1,2,3,4 and 5 were suggested by residents of Bishopstone in questionnaire responses during consultation. Site 8 was identified by a Herefordshire Council planning officer.

As a result of assessment we make the following recommendation

Sites not recommended for allocation

- Site 1 has major constraints for access and ecology and significant constraints for landscape sensitivity
- Site 2 has major constraints for access and heritage and does not conform to the Herefordshire Council Core Strategy
- Site 4 has significant constraints for heritage
- Site 5 has significant constraints for landscape sensitivity
- Site 8 has significant constraints for high landscape sensitivity and was considered unacceptable by planning officers for this reason

Site 3 is within the settlement boundary, has no major or significant constraints **Recommended for allocation**

Sites 6 and 7 which are almost adjacent were offered by the landowner in response to the Call for Sites.

• Site 6 is the smaller of the two sites and was rated with high/moderate landscape sensitivity in the SHLAA report. There are problems of access and flooding which need resolving and which would affect deliverability. Residents are opposed to the development of this site because of these problems and it was not included within the extended settlement area.

Site 6 recommended for allocation for possible long term development (15+ years) for 8 - 10 dwellings subject to mitigation of constraints.

• Site 7 (Bishon Farm) is the largest site with potential for 18 - 20 dwellings and development could be delivered within the next 5 years. The County Ecologist considers that development is the best way to preserve the remains of the traditional orchard on part of the site and the landowner has commissioned an Orchard Management Plan. Residents strongly support development and requested that the settlement boundary be extended to facilitate it. The landowner already has planning permission for conversion of barns on the site and the addition of a carefully designed development of mixed housing with a community space for residents has the potential to enhance the centre of the village and encourage community cohesion

Site 7 recommended for allocation.