Settlement Name Bodenham

Site Ref HLAA/356/001

Post Code HR13

Site Address Land North of Bunmill

Information Source Call for sites

Site Area (ha) 4.90 Potential Housing N/A Capacity	Greenfield Brownfield	Agricultural Land Classification		
Is the site suitable for development?	Is development achievable on the site	Is the site available?		
Yes \square	Yes	Yes ✓		
No 🗸	No 🗹	No \square		
Part	Part	Don't Know □		
Possible timescale for development?				
1-5 Years	11-15 Years □	Not In Current Plan Period ✓		
6-10 Years □	16-20 Years □	THE THE CANONIC FIGURE 1		

Flood information

Zone 1 - Development is appropriate. A flood risk assessment will be required for sites greater than 1 Ha. Nearby ordinary watercourses and other sources of flooding such as surface water flooding should be explored for potential flood risk.

Water information

Water Supply - DCWW Water only

Waste water and treatment- Available headroom at present (housing numbers would depend on level of headroom available)

Biodiversity information

SSSI Zone of Impact. Special Wildlife Site- close (but not adjacent) to west of site. UK BAP (Habitat of Principal Importance)- Deciduous Woodland and Traditional Orchard adjacent.

Highways information

Comments: Site appears to need access on green lane to reach unadopted track.

Conclusion: There are major issues with this site.

Site Address Land North of Bunmill

Information Source Call for sites

Landscape and Historic Environment information

Landscape Sensitivity: High - Moderate

Landscape Capacity: Low

Sensitivity & Capacity Analysis: The landscape is of a good condition, and of a high to medium value and quality locally, especially its historic character. The site is on elevated river valley slopes above village and is divorced from it. Potentially visible from views to the East and South. Development would adversely affect the conservation area & setting. Access is uncertain, but if along bridleway, adverse effects on landscape & biodiversity could be significant. Development is inappropriate in this location.

Site probability

No potential

Justification

Provision of suitable access uncertain and the sites elevated slope position and remoteness from the village make it an unsuitable location for development.

Settlement Name Bodenham

Site Ref HLAA/356/002

Post Code HR1 3

Site Address Land north of Aisling House

Information Source Call for sites

Site Area (ha) 1.70 Potential Housing 30 Capacity	Greenfield ✓ Brownfield □	Agricultural Land Classification
Is the site suitable for development?	Is development achievable on the site?	Is the site available?
Yes □	Yes	Yes ✓
No 🗆	No 🗆	No \square
Part ☑	Part ✓	Don't Know □
Possible timescale for dev 1-5 Years □ 6-10 Years ✓	11-15 Years □	n Current Plan Period

Flood information

Zone 1 - Development is appropriate. A flood risk assessment will be required for sites greater than 1 Ha. Nearby ordinary watercourses and other sources of flooding such as surface water flooding should be explored for potential flood risk.

Water information

Water Supply - DCWW Water only

Waste water and treatment- Available headroom at present (housing numbers would depend on level of headroom available.

Biodiversity information

SSSI Impact zone. No protected species or statutory habitats recorded at this location.

Highways information

Comments: Good access to both roads.

Conclusion: There are no or minor issues with this site.

Site Address Land north of Aisling House

Information Source Call for sites

Landscape and Historic Environment information

Landscape Sensitivity: High - Moderate

Landscape Capacity: Moderate

Sensitivity & Capacity Analysis: The landscape is of good condition & high to medium value and quality locally, especially its historic character. This part of the village may have limited capacity for expansion but the sensitive historic core and Listed Building settings are constraints. The site is not highly visible, but there are local views from the road & houses. The Northern third of the site is more suitable for development than the centre and South sections. Boundary vegetation should be retained and improved.

Site probability

Medium potential

Justification

Northern portion of the site more suitable for development with access potential from either of the roads.

Settlement Name Bodenham

Site Ref HLAA/356/003

Post Code HR1 3SY

Site Address Land to north of Bank House

Information Source Call for sites

Site Area (ha) 1.90 Potential Housing N/A Capacity	Greenfield ☑ Brownfield ☐	Agricultural Land Classification		
Is the site suitable for development?	Is development achievable on the site?	Is the site available?		
Yes □	Yes	Yes 🔽		
No ✓	No 🗹	No \square		
Part	Part	Don't Know □		
Possible timescale for development?				
1-5 Years	11-15 Years □	Not In Current Plan Period ✓		
6-10 Years □	16-20 Years □			

Flood information

Zone 3 (E Boundary)- Exception Test would be required

Water information

Water Supply – DCWW Water only

Waste water and treatment- Available headroom at present (housing numbers would depend on level of headroom available.

Biodiversity information

SSSI Zone of Impact. Consultation with Natural England is necessary and screening will be required. No protected species or statutory habitats recorded at this location.

Highways information

Comments: Best access via unadopted track.

Conclusion: There are some issues with this site.

Site Address Land to north of Bank House

Information Source Call for sites

Landscape and Historic Environment information

Landscape Sensitivity: High - Moderate

Landscape Capacity: Low

Sensitivity & Capacity Analysis: The landscape is of good condition & high to medium value and quality locally, especially its historic character. The site is on elevated river valley slopes above the village and is divorced from it. The site is highly visible from views to East including Bodenham Moor. Development could adversely affect the conservation area & setting as well as landscape character & visual amenity. Development is inappropriate in this location.

Site probability

No potential

Justification

The site is on the edge of the village and would represent an unacceptable extension into open countryside on an elevated slope which could impact on setting of the conservation area. There is flood risk on eastern side of site.

