Site Ref HLAA/006/001

Site Address Land east of Twinklelow Cottage, Ledbury Information Source Call for sites Road

Site Area (ha) 1.12 Potential Housing <sub>10</sub> Capacity	Greenfield	Agricultural Land Classification <sup>3</sup>
Is the site suitable for development?	Is development achievable on the site?	Is the site available?
Yes 🖌	Yes 🔽	Yes 🔽
No 🗆	No 🗌	No 🗆
Part	Part	Don't Know
Possible timescale for develo	pment?	
1-5 Years	11-15 Years	Not In Current Plan Period
6-10 Years 🗹	16-20 Years	

## **Flood information**

Zone 1 - Development is appropriate. A flood risk assessment will be required for sites greater than 1 Ha. Nearby ordinary watercourses and other sources of flooding such as surface water flooding should be explored for potential flood risk.

## Water information

Water Supply – DCWW Water only- Issues with water supply network. No capacity (improvements required) Waste water & treatment –Severn Trent- spare capacity

#### **Biodiversity information**

An ecological survey to identify biodiversity value of the field will be required. UK BAP Priority Habitat (Habitat of Principal Importance)- Deciduous Woodland approx. 20m from Eastern boundary.

#### Highways information

Comments: 30mph with no footway. Best visibility in the north west corner but land higher than the road.

Conclusion: There are some issues with access.

Site Address Land east of Twinklelow Cottage, Ledbury Information Source Call for sites Road

#### Landscape and Historic Environment information

Landscape Sensitivity: Moderate Landscape Capacity: Low - Moderate

Sensitivity & Capacity Analysis: The site is on a West sloping field - which is overgrown with weeds and ground cover. It has a semi-enclosed character. There is a native hedgerow on the Western boundary running adjacent and parallel to the road. There are medium distance views to the West. The land is approximately 1.5m above the level of the road.

## Site probability

Medium potential

#### Justification

Settlement pattern consists of isolated cottages in this location. Site integration would take time but could be possible as the site is generally contained. There are some issues with access as the site is higher than the road. Some potential contamination (quarrying) requires assessing.

Site Ref HLAA/013/001

Site Address Land west and north to Farmers Arms public house

Information Source Call for sites

Site Area (ha) 0.63 Potential Housing <sub>N/A</sub> Capacity	Greenfield Brownfield	<ul> <li>Agricultural Land Classification <sup>3</sup></li> </ul>
Is the site suitable for development?	Is development achievable on the site	Is the site available? e?
Yes 🗌	Yes 🗌	Yes 🔽
No 🖌	No 🔽	No
Part	Part	Don't Know
Possible timescale for develo	pment?	
1-5 Years	11-15 Years	Not In Current Plan Period 🛛 🗹
6-10 Years	16-20 Years	

# **Flood information**

Zone 1 - Development is appropriate. A flood risk assessment will be required for sites greater than 1 Ha. Nearby ordinary watercourses and other sources of flooding such as surface water flooding should be explored for potential flood risk.

## Water information

Water Supply – DCWW Water only- Issues with water supply network. No capacity (improvements required) Waste water & treatment –Severn Trent- spare capacity

## **Biodiversity information**

UK BAP Priority Habitat (Habitat of Principal Importance)- approx 60m to the North West part of site.

## Highways information

Comments: Access difficult via unmade narrow track with no footway.

Conclusion: There are major issues with this site.

Site Address Land west and north to Farmers Arms public house

Information Source Call for sites

#### Landscape and Historic Environment information

Landscape Sensitivity: High - Moderate Landscape Capacity: Low

Sensitivity & Capacity Analysis: The site is a grassland field sloping steeply to the East. It features a broken native hedgerow on the Western boundary, parallel and adjacent to the lane. There are medium distance views to the East.

## Site probability

No potential

#### Justification

Due to difficulties with access this site is not deemed to have potential within the SHLAA.

Site Ref HLAA/026/001

Site Address The Swallows Farm Stables Estate

Information Source Call for sites

Site Area (ha) 6.01 Potential Housing <sub>N/A</sub> Capacity	Greenfield Brownfield	Agricultural Land Classification <sup>3</sup>
Is the site suitable for development?	Is development achievable on the site	Is the site available? ?
Yes 🗌	Yes 🗌	Yes 🔽
No 🔽	No 🖌	No 🗆
Part	Part	Don't Know
Possible timescale for develo	pment?	
1-5 Years	11-15 Years	Not In Current Plan Period
6-10 Years	16-20 Years	

## **Flood information**

Zone 1 - Development is appropriate. A flood risk assessment will be required for sites greater than 1 Ha. Nearby ordinary watercourses and other sources of flooding such as surface water flooding should be explored for potential flood risk.

## Water information

Water Supply – DCWW Water only- Issues with water supply network. No capacity (improvements required) Waste water & treatment –Severn Trent- spare capacity

## **Biodiversity information**

UK BAP Priority Habitat (Habitat of Principal Importance)- Deciduous Woodland- Small area abutts center of Southern boundary.

## Highways information

Comments: Reasonable visibility between Swallow Farm and 30 limit (NW boundary) but better visibility to North East corner. Road 30mph with no footway to west. Derestricted road with no footway to east.

Conclusion: There are some issues with this site.

Site Address The Swallows Farm Stables Estate

Information Source Call for sites

#### Landscape and Historic Environment information

Landscape Sensitivity: High Landscape Capacity: Low

Sensitivity & Capacity Analysis: The site is a grassland field with horses in it, sloping mainly towards the East, with long distance views to the East, North and South. There are mature native hedgerows on the Southern boundary.

## Site probability

No potential

#### Justification

This is a highly sensitive site in AONB landscape and therefore the site is unsuitable for development. Development would be a protrusion into the landscape.

#### Site Address Land south of Hilltop House

Information Source Call for sites

Site Area (ha) 2.15 Potential Housing <sub>N/A</sub> Capacity	Greenfield Brownfield	Agricultural Land Classification <sup>3</sup>
Is the site suitable for development?	Is development achievable on the site	Is the site available? ?
Yes 🗌	Yes	Yes 🔽
No 🖌	No 🔽	No 🗆
Part	Part	Don't Know
Possible timescale for develo	pment?	
1-5 Years	11-15 Years	Not In Current Plan Period
6-10 Years	16-20 Years	

## **Flood information**

Zone 1 - Development is appropriate. A flood risk assessment will be required for sites greater than 1 Ha. Nearby ordinary watercourses and other sources of flooding such as surface water flooding should be explored for potential flood risk.

## Water information

Water Supply - DCWW Water only- Issues with water supply network. No capacity (improvements required) Waste water & treatment -Severn Trent- spare capacity

#### **Biodiversity information**

UK BAP Priority Habitat (Habitat of Principal Importance)- Frith Wood to South East of site.

## **Highways information**

Comments: Road derestricted and visibility slightly restricted to left. May need hedge out (subject to Hedgerow Regulations). No footway.

Conclusion: There are some issues with this site.

Site Address Land south of Hilltop House

#### Landscape and Historic Environment information

Landscape Sensitivity: High Landscape Capacity: Low

Sensitivity & Capacity Analysis: The site is a grassland field sloping towards the East. It has an enclosed character. There are trees along its boundaries, with access restrictions.

## Site probability

No potential

#### Justification

The site is divorced from the main settlement. Due to high landscape value, development of the site would be unacceptable.

Site Address Land at junction of Church Lane and Burton Lane

Information Source LA officer identified

Site Area (ha) 0.32	Greenfield	✓ Agricultural Land
Potential Housing <sub>N/A</sub> Capacity	Brownfield	Classification 3
Is the site suitable for development?	Is development achievable on the site	Is the site available? e?
Yes 🗌	Yes 🗌	Yes 🗌
No 🗹	No 🔽	No
Part	Part	Don't Know 🔽
Possible timescale for develop	pment?	
1-5 Years	11-15 Years	Not In Current Plan Period 🛛 🔽
6-10 Years	16-20 Years	

## **Flood information**

Zone 1 - Development is appropriate. A flood risk assessment will be required for sites greater than 1 Ha. Nearby ordinary watercourses and other sources of flooding such as surface water flooding should be explored for potential flood risk.

## Water information

Water Supply – DCWW Water only- Issues with water supply network. No capacity (improvements required) Waste water & treatment –Severn Trent- spare capacity

## **Biodiversity information**

UK BAP Priority Habitat (Habitat of Principal Importance)- Traditional Orchard covering Western half of site.

## Highways information

Comments: On boundary of 30mph speed limit/derestricted road. Visibility poor due to gentle curve of road. Would need removal of frontage hedge(subject to hedgerow regulations). No footway.

Conclusion: There are some issues with this site.

Site Address Land at junction of Church Lane and Burton Lane

Information Source LA officer identified

#### Landscape and Historic Environment information

Landscape Sensitivity: Moderate - High Landscape Capacity: Low - Moderate

Sensitivity & Capacity Analysis: The site is an unmaintained grassland field, with a maintained native hedgerow on its Southern boundary parallel and adjacent to the road. Some old orchard trees are on the site, and there is woodland to the North of the site. The site has an enclosed character.

## Site probability

No potential

#### Justification

Western half of site contains a traditional Orchard BAP. The remainder of the site would not be large enough to yield 5 dwellings and therefore is not a suitable SHLAA site.

Site Address Land east of cemetary, Church Lane

Information Source LA officer identified

Site Area (ha) 0.75 Potential Housing <sub>N/A</sub> Capacity	Greenfield ✓ Brownfield □	Agricultural Land Classification <sup>3</sup>
Is the site suitable for development?	Is development achievable on the site?	Is the site available?
Yes 🗆	Yes 🗌	Yes 🗌
No 🔽	No 🔽	No 🗆
Part	Part	Don't Know 🗹
Possible timescale for devel	opment?	
1-5 Years	11-15 Years 🛛 🛛	ot In Current Plan Period
6-10 Years	16-20 Years	

## **Flood information**

Zone 1 - Development is appropriate. A flood risk assessment will be required for sites greater than 1 Ha. Nearby ordinary watercourses and other sources of flooding such as surface water flooding should be explored for potential flood risk.

## Water information

Water Supply – DCWW Water only- Issues with water supply network. No capacity (improvements required) Waste water & treatment –Severn Trent- spare capacity

## **Biodiversity information**

UK BAP Priority Habitat (Habitat of Principal Importance)- Deciduous Woodland close to South East corner of site.

## **Highways information**

Comments: 'C' Class Road 30mph limit. No footway. Visibility very poor both ways.

Conclusion: There are major issues with this site.

Site Address Land east of cemetary, Church Lane

Information Source LA officer identified

#### Landscape and Historic Environment information

Landscape Sensitivity: High Landscape Capacity: Low

Sensitivity & Capacity Analysis: The site is a domed grassland field, sloping to the South and West. It has an enclosed character. It has a native hedgerow adjacent and parallel to the road. It is an intimate space. Woodland lies to the Northern boundary.

## Site probability

No potential

#### Justification

Due to highly sensitive landscape and inadequate visibility in both directions for this site, it is not considered suitable for development.

Site Address Land north of junction of Church Lane and Information Source LA officer identified The Common

Site Area (ha) 0.67 Potential Housing <sub>N/A</sub> Capacity	Greenfield ✓ Brownfield	Agricultural Land Classification <sup>3</sup>
Is the site suitable for development?	Is development achievable on the site?	Is the site available?
Yes 🗌	Yes	Yes 🗆
No 🔽	No 🔽	No 🗆
Part	Part	Don't Know 🗹
Possible timescale for deve	elopment?	
1-5 Years	11-15 Years	lot In Current Plan Period
6-10 Years	16-20 Years	

## **Flood information**

Zone 1 - Development is appropriate. A flood risk assessment will be required for sites greater than 1 Ha. Nearby ordinary watercourses and other sources of flooding such as surface water flooding should be explored for potential flood risk.

#### Water information

Water Supply – DCWW Water only- Issues with water supply network. No capacity (improvements required) Waste water & treatment –Severn Trent- spare capacity

#### **Biodiversity information**

UK BAP Priority Habitat (Habitat of Principal Importance)- Deciduous Woodland approximately 50m to North West of site.

#### Highways information

Comments: 30 mph limit. No footway. Reasonable visibility can be achieved in south east corner.

Conclusion: There are no or minor issues with this site.

Site Address Land north of junction of Church Lane and Information Source LA officer identified The Common

#### Landscape and Historic Environment information

Landscape Sensitivity: High Landscape Capacity: Low

Sensitivity & Capacity Analysis: The site is a grassland field, sloping to the North. It is framed by woodland on the East and West boundaries. There are long distance views to the North. A narrow woodland belt lies on the Southern boundary.

#### Site probability

No potential

#### Justification

Due to the highly sensitive landscape of this site, development here would be inappropriate.

Site Address Land north of Raycombe Lane

Information Source LA officer identified

Site Area (ha) 0.39 Potential Housing <sub>N/A</sub> Capacity	Greenfield Brownfield □	Agricultural Land Classification <sup>3</sup>
Is the site suitable for development?	Is development achievable on the site?	Is the site available?
Yes 🗌	Yes 🗆	Yes 🗌
No 🔽	No 🔽	No 🗆
Part	Part	Don't Know 🔽
Possible timescale for c	levelopment?	
1-5 Years	11-15 Years	lot In Current Plan Period
6-10 Years	16-20 Years	

## **Flood information**

Zone 1 - Development is appropriate. A flood risk assessment will be required for sites greater than 1 Ha. Nearby ordinary watercourses and other sources of flooding such as surface water flooding should be explored for potential flood risk.

## Water information

Water Supply – DCWW Water only- Issues with water supply network. No capacity (improvements required) Waste water & treatment –Severn Trent- spare capacity

## **Biodiversity information**

No protected species or statutory habitats recorded at this location.

## Highways information

Comments: 30mph limit no footway. Visibility restricted by hedge to site which would require removal (subject to hedgerow regulations).

Conclusion: There are some issues with this site.

**Site Address** Land north of Raycombe Lane

#### Landscape and Historic Environment information

Landscape Sensitivity: High Landscape Capacity: Low

Sensitivity & Capacity Analysis: The site is a grassland field, approximately 2m above the adjacent road on the Southern boundary. The field is domed and slopes to the South, towards which there are long-distance views. Woodland lies on the Western boundary.

## Site probability

No potential

## Justification

Due to the highly sensitive landscape of this site and the need for hedgerow removal, development here would be inappropriate.

#### Site Address Land west of The Swallows

Information Source LA officer identified

Site Area (ha) 0.57 Potential Housing <sub>N/A</sub> Capacity	Greenfield Brownfield	Agricultural Land Classification <sup>3</sup>
Is the site suitable for development?	Is development achievable on the site	Is the site available? ?
Yes 🗌	Yes	Yes 🗆
No 🗹	No 🔽	No 🗆
Part	Part	Don't Know 🗹
Possible timescale for develo	pment?	
1-5 Years	11-15 Years	Not In Current Plan Period
6-10 Years	16-20 Years	

## **Flood information**

Zone 1 - Development is appropriate. A flood risk assessment will be required for sites greater than 1 Ha. Nearby ordinary watercourses and other sources of flooding such as surface water flooding should be explored for potential flood risk.

#### Water information

Water Supply – DCWW Water only- Issues with water supply network. No capacity (improvements required) Waste water & treatment –Severn Trent- spare capacity

#### **Biodiversity information**

UK BAP Priority Habitat (Habitat of Principal Importance)- Deciduous Woodland close to South West corner approximately 50m from Western boundary of site.

#### **Highways information**

Comments: Two access points. Best one to east (The Common). Road wide but no footway. 30mph limit. Visibility good.

Conclusion: There are no or minor issues with this site.

Site Address Land west of The Swallows

Information Source LA officer identified

#### Landscape and Historic Environment information

Landscape Sensitivity: High Landscape Capacity: Low

Sensitivity & Capacity Analysis: The site comprises woodland sloping to the East, with semi-mature trees. A native hedgerow lies parallel and adjacent to the road on the Eastern boundary. A high biodiversity value site.

## Site probability

No potential

#### Justification

Woodland sloping to the east. Semi mature trees with native hedgerow parallel and adjacent to the road on the eastern boundary. Due to the highly sensitive landscape of this site development here would be inappropriate.

Site Address Land east of Ochre Hill

Information Source LA officer identified

Site Area (ha) 1.20 Potential Housing <sub>N/A</sub> Capacity	Greenfield ✓ Brownfield □	Agricultural Land Classification <sup>3</sup>
Is the site suitable for development?	Is development achievable on the site?	Is the site available?
Yes 🗌	Yes	Yes 🗆
No 🔽	No 🔽	No 🗆
Part	Part	Don't Know 🔽
Possible timescale for deve	elopment?	
1-5 Years	11-15 Years	ot In Current Plan Period 🛛 🔽
6-10 Years	16-20 Years	

## **Flood information**

Zone 1 - Development is appropriate. A flood risk assessment will be required for sites greater than 1 Ha. Nearby ordinary watercourses and other sources of flooding such as surface water flooding should be explored for potential flood risk.

## Water information

Water Supply – DCWW Water only- Issues with water supply network. No capacity (improvements required) Waste water & treatment –Severn Trent- spare capacity

## **Biodiversity information**

UK BAP Priority Habitat (Habitat of Principal Importance)- Deciduous Woodland approximately 80m to the North East of site. High biodiversity value site and will require assessment.

## Highways information

Comments: Good access to unmade road but route via Ochre Hill very narrow, limited visibility and no footway.

Conclusion: There are major issues with this site.

Site Address Land east of Ochre Hill

Information Source LA officer identified

#### Landscape and Historic Environment information

Landscape Sensitivity: High Landscape Capacity: Low

Sensitivity & Capacity Analysis: The site is grass field sloping gently to the East. It has a well maintained native hedgerow on the Western boundary adjacent and parallel to the lane. There are access restrictions.

## Site probability

No potential

## Justification

Not a suitable site in landscape terms due to its high sensitivity. Additional difficulties with route to the site being too narrow to accommodate housing development traffic.

Site Address Land south east of Ochre Hill

Information Source LA officer identified

Site Area (ha) 10.92 Potential Housing <sub>N/A</sub> Capacity	Greenfield	Agricultural Land Classification <sup>3</sup>
Is the site suitable for development?	Is development achievable on the site?	Is the site available?
Yes 🗌	Yes 🗌	Yes 🗌
No 🔽	No 🔽	No 🗆
Part	Part	Don't Know 🗹
Possible timescale for de	evelopment?	
1-5 Years	11-15 Years	ot In Current Plan Period 🛛 🔽
6-10 Years	16-20 Years	

## **Flood information**

Zone 1 - Development is appropriate. A flood risk assessment will be required for sites greater than 1 Ha. Nearby ordinary watercourses and other sources of flooding such as surface water flooding should be explored for potential flood risk.

## Water information

Water Supply – DCWW Water only- Issues with water supply network. No capacity (improvements required) Waste water & treatment –Severn Trent- spare capacity

## **Biodiversity information**

UK BAP Priority Habitat (Habitat of Principal Importance)- Deciduous Woodland adjoins North West boundary of site.

## Highways information

Comments: Limited access. Only route to south west corner is far too narrow. Needs third party land.

Possible mitigation: Link through 010 and 011 to 029/001.

Conclusion: There are major issues with this site.

Site Address Land south east of Ochre Hill

Information Source LA officer identified

#### Landscape and Historic Environment information

Landscape Sensitivity: High Landscape Capacity: Low

Sensitivity & Capacity Analysis: The site comprises a grassland field sloping to the East with cattle. There are long distance views to the South. It features well maintained native hedgerows.

## Site probability

No potential

#### Justification

Not a suitable site in landscape terms due to its high sensitivity. Additional difficulties with route to the site being too narrow to accommodate housing development traffic.

Site Address Land east of Horse Road

Information Source LA officer identified

Site Area (ha) 1.57 Potential Housing <sub>N/A</sub> Capacity	Greenfield Image: Second state of the secon	Agricultural Land Classification <sup>3</sup>
Is the site suitable for development?	Is development achievable on the site?	Is the site available?
Yes 🗌	Yes 🗌	Yes 🗌
No 🔽	No 🔽	No 🗆
Part	Part	Don't Know 🔽
Possible timescale for deve	lopment?	
1-5 Years	11-15 Years 🛛 🗌	ot In Current Plan Period 🛛 🔽
6-10 Years	16-20 Years	

## **Flood information**

Zone 1 - Development is appropriate. A flood risk assessment will be required for sites greater than 1 Ha. Nearby ordinary watercourses and other sources of flooding such as surface water flooding should be explored for potential flood risk.

## Water information

Water Supply – DCWW Water only- Issues with water supply network. No capacity (improvements required) Waste water & treatment –Severn Trent- spare capacity

## **Biodiversity information**

UK BAP Priority Habitat (Habitat of Principal Importance)- Deciduous Woodland- 'Frithwood' to South East of site.

## Highways information

Comments: Best access is to west side if no ransom issue, visiblity good. Access to north too narrow.

Conclusion: There are some issues with this site.

Site Address Land east of Horse Road

Information Source LA officer identified

#### Landscape and Historic Environment information

Landscape Sensitivity: High Landscape Capacity: Low

Sensitivity & Capacity Analysis: The site comprises grassland sloping from the North to the South. It features tree hedgerows, and long and medium distance views to the South and East. Electric pylon wires run in approximately a North/South direction across the site.

## Site probability

No potential

## Justification

Due to the highly sensitive landscape of this site, development here would be inappropriate.

#### Site Address Land south east of Horse Road

Information Source LA officer identified

Site Area (ha) 1.99 Potential Housing <sub>N/A</sub> Capacity	Greenfield	Agricultural Land Classification <sup>3</sup>
Is the site suitable for development?	Is development achievable on the site?	Is the site available?
Yes 🗆	Yes	Yes 🗌
No 🗹	No 🔽	No 🗆
Part	Part	Don't Know 🔽
Possible timescale for development?		
1-5 Years	11-15 Years	t In Current Plan Period
6-10 Years	16-20 Years	

## **Flood information**

Zone 1 - Development is appropriate. A flood risk assessment will be required for sites greater than 1 Ha. Nearby ordinary watercourses and other sources of flooding such as surface water flooding should be explored for potential flood risk.

## Water information

Water Supply – DCWW Water only- Issues with water supply network. No capacity (improvements required) Waste water & treatment –Severn Trent- spare capacity

#### **Biodiversity information**

UK BAP Priority Habitat (Habitat of Principal Importance)- Deciduous Woodland to North West approximately 100m away.

#### Highways information

Comments: Only access to north if no third party issues, visibility good.

Verdict: Some issues

Site Address Land south east of Horse Road

#### Landscape and Historic Environment information

Landscape Sensitivity: High Landscape Capacity: Low

Sensitivity & Capacity Analysis: The site is a grassland field sloping to the South with sheep. An electric pylon wire runs in approximately an East-West direction. There is a tree hedgerow on its Eastern boundary. A new dwelling lies on the Northern boundary. There are medium distance views to the East.

## Site probability

No potential

#### Justification

Due to the highly sensitive landscape of this site, development here would be inappropriate.

