
### Herefordshire Schools Capital Investment Strategy

# Hereford City - South Jan 2016





**Our Lady's RC Primary School** 






**Riverside Primary School** 




St Martin's Primary School

### Proximity of schools - distances




**Distance in miles** 

### Number on roll 2008 – 2015




#### Suitability of the sites and buildings

Site Area Compliance %






Site Area Compliance %




Site Area Compliance 153%



#### Suitability of the sites and buildings


#### Capacity and numbers on roll




Allocated Capacity used for Compliance max min

average roll

#### **Number Roll & Parent Preference**



### **Current NOR by School Year**



Marlbrook Primary School	60	90	90	61	59	60	60	60
Our Lady's RC Primary School	30	31	30	30	30	31	22	24
Riverside Primary School	90	76	92	91	76	78	43	55
St Martin's Primary School	60	38	59	54	42	62	45	27
Area Total NOR	240	235	271	236	207	231	170	166



### Summary of key issues for Hereford City -South

- Overall numbers on roll increasing (250 more since 2008)
- Riverside is a modern/new school now filling up in lower year groups.
- Schools north of the river and rural east Hereford draw children from this area.
- Marlbrook (outstanding school) parent first preferences regularly exceeding PAN
- Significant investment required in St Martin's and Our Lady's which are tired buildings, rolls either static or decreasing.
- 1000 new homes at Lower Bullingham planned

### What next?

### Options

- Do nothing
- Re-build, extend Marlbrook on current site to create an extra form of entry.
- Explore consolidation, renewal, build options for St Martins, Our Lady's and the demand linked to housing

### **Considerations and risks**

- Future reactive costs at St Martins and Our Lady's
- New school may change migration patterns.
- Parent preference met
- Neither Our Lady's nor St Martins site suitable for consolidation

### Suggested way forward

- Engage in discussion with all stakeholders about the way forward for Marlbrook primary school, consider the bigger picture regarding demand, capacity needed in the south of the city, and migration of south wye children to the rural east.
- Consult with all head teachers, governors and the wider community regarding the best solution to address the pressing compliance and condition issues at St Martins primary school and Our Lady's primary school.



# Summary and initial options analysis July 2015






#### **Existing school information**

Site	214% compliant at 38,569m <sup>2</sup> (100% = 17,983m <sup>2</sup> )
Building (against PAN of 60– capacity 420)	101% compliant at 2,138m <sup>2</sup> (100% = 2,111m <sup>2</sup> ) Correct number of classrooms at 14 (11 small) 3 temporary buildings (2 classrooms in temporary buildings)
Maintenance work	£38k over 5 years including backlog
Occupancy and demand	<ul> <li>Increasing roll (386 in 2008 increased to 405 in 2010 now 445)</li> <li>Nearest school for 1,075 children</li> <li>346 on roll for whom it is the nearest school</li> <li>99 on roll for whom it is not the nearest are mainly drawn from no particular school</li> <li>729 for whom it is the nearest mainly go to Riverside</li> <li>First preference</li> <li>September 2015 - 115</li> <li>September 2014 - 105</li> </ul>
Inspection /outcomes	2009 inspection rated Outstanding
Energy consumption	Total energy rating is average
Disability access	Rate 2 – Mainly accessible



#### Site plan





Options an	d ideas to achieve principles	Comment
Site	<ul><li>Expand school size on site</li><li>Increase PAN</li></ul>	<ul> <li>60 to 90 i.e. a total of 630 (nearest school for 1075 pupils)</li> </ul>
Building	<ul> <li>Expand building to achieve increased PAN compliance requirements</li> </ul>	
Maintenance and efficiency	<ul> <li>Ensure school has a 5 year maintenance plan in place</li> </ul>	
Occupancy	<ul> <li>Ensure school maintains the current annual increase in NOR</li> </ul>	
Leadership	Shared leadership is already in place	

Future housing - 2031	Implication for school
Total development in catchment area - 1046 houses	Predicted primary children – 181



# Our Lady's RC Primary School

# Summary and initial options analysis July 2015



### Our Lady's RC Primary School




#### **Existing school information**

Site	212% compliant at 21,400m <sup>2</sup> updated to include Archdiocese playing field as well as LA owned playing field (100% = 10,116m <sup>2</sup> )
Building (against PAN of 30– capacity 210)	<ul> <li>111% compliant at 1,364m<sup>2</sup> (100% = 1,225m<sup>2</sup>)</li> <li>Correct number of classrooms at 7 ( 4 small)</li> <li>2 temporary buildings (no classrooms in temporary buildings)</li> </ul>
Maintenance work	£364k over 5 years including backlog
Occupancy and demand	<ul> <li>Fluctuating roll (210 in 2008 decreased to 185 in 2010 now 192 {Autumn 2015})</li> <li>Nearest school for 397 children {Autumn 2014}</li> <li>32 on roll for whom it is the nearest school</li> <li>160 on roll for whom it is not the nearest are mainly drawn from Marlbrook, St Martin's and Riverside</li> <li>365 for whom it is the nearest mainly go to St Martin's and Riverside</li> <li>First preference</li> <li>September 2015 - 33</li> <li>September 2014 - 40</li> </ul>
Inspection /outcomes	2013 inspection rated Good
Energy consumption	Total energy rating is average
Disability access	Rate 2 – Mainly accessible



### **Our Lady's RC Primary School**

#### Site plan





## **Our Lady's RC Primary School**

Options an	d ideas to achieve principles	Comment
Site	Sell off surplus site area	
Building	Do nothing	
Maintenance and efficiency	<ul> <li>Ensure school has a 5 year maintenance p in place</li> </ul>	lan
Occupancy	Ensure school maintains current NOR	
Leadership	<ul> <li>Is currently standalone and options to formally federate or have alternative management/leadership could be explore</li> </ul>	d
Future hou	sing - 2031	Implication for school
Total development in catchment area – 1000 houses		Predicted primary children – 174



# Summary and initial options analysis July 2015





#### **Existing school information**

Site	153% compliant at 39,650m <sup>2</sup> (100% = 25,850m <sup>2</sup> )
Building (against PAN of 90– capacity 630)	113% compliant at 3,364m <sup>2</sup> (100% = 2,976m <sup>2</sup> ) Correct number of classrooms at 21 ( no small) No temporary buildings (no classrooms in temporary buildings)
Maintenance work	Not available
Occupancy and demand	<ul> <li>Increasing roll (331 in 2008 decreased to 324 in 2010 now 482)</li> <li>Nearest school for 428 children</li> <li>127 on roll for whom it is the nearest school</li> <li>355 on roll for whom it is not the nearest are mainly drawn from Marlbrook</li> <li>301 for whom it is the nearest mainly go to Lord Scudamore</li> <li>First preference</li> <li>September 2015 - 74</li> <li>September 2014 - 69</li> </ul>
Inspection /outcomes	2014 inspection rated Good
Energy consumption	Total energy rating is average
Disability access	Rate 3 – Fully accessible



#### Site plan





Options an	d ideas to achieve principles	Comment
Site	Sell off surplus site area	
Building	• Do nothing	Relatively new school
Maintenance and efficiency	<ul> <li>N/A – no information yet available</li> </ul>	
Occupancy	Continue to increase NOR	
Leadership	<ul> <li>Is currently standalone and options to formally federate or have alternative management/leadership could be explored</li> </ul>	

Future housing - 2031	Implication for school
Total development in catchment area – 1608 houses	Predicted primary children – 280



# Summary and initial options analysis July 2015






#### **Existing school information**

Site	118% compliant at 21,157m <sup>2</sup> (100% = 17,983m <sup>2</sup> )
Building (against PAN of 60– capacity 420)	<ul> <li>114% compliant at 2,417m<sup>2</sup> (100% = 2,111m<sup>2</sup>)</li> <li>Correct number of classrooms at 15 (15 small)</li> <li>1 temporary buildings (no classrooms in temporary buildings)</li> </ul>
Maintenance work	£926k over 5 years including backlog
Occupancy and demand	<ul> <li>Fluctuating roll (338 in 2008 decreased to 319 in 2010 now 323)</li> <li>Nearest school for 205 children</li> <li>87 on roll for whom it is the nearest school</li> <li>236 on roll for whom it is not the nearest are mainly drawn from Marlbrook</li> <li>118 for whom it is the nearest mainly go to Marlbrook, Our Lady's RC and Riverside</li> <li>First preference</li> <li>September 2015 - 32</li> <li>September 2014 - 34</li> </ul>
Inspection /outcomes	2013 inspection rated Requires Improvement
Energy consumption	Total energy rating is average
Disability access	Rate 3 – Fully accessible



#### Site plan





Options an	d ideas to achieve principles	Comment
Site	Do nothing	
Building	Do nothing	
Maintenance and efficiency	Ensure school has a 5 year maintenance plan in place	• NB - £900K+ over 5 years
Occupancy	<ul> <li>Increase NOR to ensure school is within PAN allocation</li> </ul>	
Leadership	<ul> <li>Is currently standalone and options to formally federate or have alternative management/leadership could be explored</li> </ul>	

Future housing - 2031	Implication for school
Total development in catchment area – 1021 houses	Predicted primary children – 178



# The Hereford Academy School

# Summary and initial options analysis July 2015



### **The Hereford Academy**




#### **Existing school information**

Site	84% compliant at 61,277m <sup>2</sup> (100% = 73,037m <sup>2</sup> )	
Building (against PAN of 180 x 5 & 110 x 2 – capacity 1,120)	97% compliant at 8,985m <sup>2</sup> (100% = 9,215m <sup>2</sup> )	
Maintenance work	Not available	
Occupancy and demand	<ul> <li>Fluctuating roll (693 in 2008 increased to 731 in 2010 now 682)</li> <li>Nearest school for 1,368 children</li> <li>734 on roll for whom it is the nearest school</li> <li>150 on roll for whom it is not the nearest are mainly drawn from no particular school</li> <li>634 for whom it is the nearest mainly go to Bishops</li> <li>First preference</li> <li>September 2015 - 139</li> <li>September 2014 - 171</li> </ul>	
Inspection /outcomes	2013 inspection rated Inadequate	
Energy consumption	Total energy rating is significantly above average	
Disability access	Rate 3 – Fully accessible	



### **The Hereford Academy**

#### Site plan





### **The Hereford Academy**

Options and ideas to achieve principles		Comment
Site	Do nothing	
Building	• Do nothing	
Maintenance and efficiency	<ul> <li>N/A – no information available</li> </ul>	
Occupancy	Increase NOR to ensure school is within Pa allocation	AN
Leadership	<ul> <li>Is currently standalone and options to formally federate or have alternative management/leadership could be explore</li> </ul>	d
Future housing - 2031		Implication for school
Total development in catchment area - 1675 houses		Predicted secondary children – 223