

FUME SYSTEM INSPECTION SERVICE

CLEAN AIR DUST AND FUME EXTRACTION LTD

25a, Lane Street, Bradley, Bilston WV14 8UT

Tel: 07734 228 441

Email: cleanairltd@hotmail.co.uk

COSHH CERTIFICATE CC

EXAMINATION OF LOCAL EXHAUST VENTILATION PLANT

LEV 1

Name of company/agent	JRC LTD
Plant address	Longmead Elms Green Leominster Herefordshire HR6 0NS

Minimum test frequency 14 months

Date of inspection	15 th May 2019
Date of previous inspection	Not Known
Inspector	Ian Sherwood

EQUIPMENT

Manufacturer	Airflow
Model	Belt driven spray booth fan 630 dia
Serial no. or user I.D.	LEV1
Description	A spray booth with cardboard filter 4300 long 900 high
Fan type	Belt driven
Filtration system	Cardboard concertina
Motor power & voltage	N/A

INSPECTION RESULTS

Fumes collected	Paint
Fit for purpose	yes
Operator competence	good
Equipment condition	Good
Inspection results	Air velocity reading taken in 12 places across filter section 1.7 average
If equipment has failed, work required to bring into good working order.	PASSED

All air velocity readings taken with a Kestrel Anemometer type K1000, s/n 437444, last calibrated 1st June 2018

DATE 07/04/2019

Signed *Ian Sherwood*

FUME SYSTEM INSPECTION SERVICE

CLEAN AIR DUST AND FUME EXTRACTION LTD

25a, Lane Street, Bradley, Bilston WV14 8UT

Tel: 07734 228 441

Email: cleanairltd@hotmail.co.uk

COSHH CERTIFICATE cc

EXAMINATION OF LOCAL EXHAUST VENTILATION PLANT

LEV 2

Name of company/agent	JRC LTD
Plant address	Longmead Elms Green Leominster Herefordshire HR6 0NS

Minimum test frequency 14 months

Date of inspection	15 th May 2019
Date of previous inspection	Not Known
Inspector	Ian Sherwood

EQUIPMENT

Manufacturer	Airflow
Model	Belt driven spray booth fan 630 dia
Serial no. or user I.D.	LEV2
Description	A spray booth with cardboard filter 4300 long 900 high
Fan type	Belt driven
Filtration system	Cardboard concertina
Motor power & voltage	N/A

INSPECTION RESULTS

Fumes collected	Paint
Fit for purpose	yes
Operator competence	good
Equipment condition	Good
Inspection results	Air velocity reading taken in 12 places across filter section 1.8 average
If equipment has failed, work required to bring into good working order.	PASSED

All air velocity readings taken with a Kestrel Anemometer type K1000, s/n 437444, last calibrated 1st June 2018

DATE 07/04/2019

Signed *Ian Sherwood*

FUME SYSTEM INSPECTION SERVICE

CLEAN AIR DUST AND FUME EXTRACTION LTD

25a, Lane Street, Bradley, Bilston WV14 8UT

Tel: 07734 228 441

Email: cleanairltd@hotmail.co.uk

COSHH CERTIFICATE CC

EXAMINATION OF LOCAL EXHAUST VENTILATION PLANT

LEV 3

Name of company/agent	JRC LTD
Plant address	Longmead Elms Green Leominster Herefordshire HR6 0NS

Minimum test frequency 14 months

Date of inspection	15 th May 2019
Date of previous inspection	Not Known
Inspector	Ian Sherwood

EQUIPMENT

Manufacturer	Airflow
Model	Belt driven spray booth fan 630 dia
Serial no. or user I.D.	LEV 3
Description	A spray booth with cardboard filter 4300 long 900 high
Fan type	Belt driven
Filtration system	Cardboard concertina
Motor power & voltage	N/A

INSPECTION RESULTS

Fumes collected	Paint
Fit for purpose	yes
Operator competence	good
Equipment condition	Good
Inspection results	Air velocity reading taken in 12 places across filter section 1.8 average
If equipment has failed, work required to bring into good working order.	PASSED

All air velocity readings taken with a Kestrel Anemometer type K1000, s/n 437444, last calibrated 1st June 2018

DATE 07/04/2019

Signed *Ian Sherwood*