Site Address The Sling, Staunton on Wye

Information Source Call for sites

Site Area (ha) 0.41 Potential Housing _{N/A} Capacity	Greenfield	Agricultural Land Classification ¹
Is the site suitable for development?	Is development achievable on the site?	Is the site available?
Yes 🗌	Yes	Yes 🔽
No 🗹	No 🖌	No 🗆
Part	Part	Don't Know
Possible timescale for development?		
1-5 Years	11-15 Years	Not In Current Plan Period 🛛 🔽
6-10 Years	16-20 Years	

Flood information

Zone 1 - Development is appropriate. A flood risk assessment will be required for sites greater than 1 Ha. Nearby ordinary watercourses and other sources of flooding such as surface water flooding should be explored for potential flood risk.

Water information

Limited capacity at present

Biodiversity information

No protected species or statutory habitats recorded at this location.

Highways information

Comments: Access track to site compromised by width and 90 degree bend.'C' class road access also narrow, no footways.

Conclusion: There are major issues with this site.

Site Address The Sling, Staunton on Wye

Landscape and Historic Environment information

Landscape Sensitivity: Low - Moderate Landscape Capacity: Moderate

Sensitivity & Capacity Analysis: The site does not relate well to the existing settlement, its Northerly slope further links it with open countryside. The site is a long narrow strip of land not conductive to a layout for development.

Site probability

No potential

Justification

The site's location makes it unsuitable as it has poor links with the village and there are major issues with accessing the site. The shape of this site presents problems in terms of achieving a suitable layout that would deliver five or more houses.

