

Settlement Pudleston Site Reference HLAA/141/001 Site Address Land adjacent to Tan House Cottages Post Code HR6 0QY

Basic Information							
Source Call for	sites Site Area (ha	2.85	Greenfield/Brownfield?	Greenfield	Agricultural Land Classification	3	
				□ Brownfield			

Technical Assessment

Flood Risk

Zone 1- Development is appropriate. A flood risk assessment will be required for sites greater than 1 ha in size. Nearby ordinary water courses and other sources of flooding, such as surface water flooding, should be explored for potential flood risk.

Water Information

Operator(s): Dwr Cymru Welsh Water (WS)

Water Supply (WS): Welsh Water will provide comment as part of the Rural Areas Site Allocation Development Plan Document consultation. Wastewater Treatment Works (WwTW): Not known- private sewer

Biodiversity Information

Habitat of Principal Importance- Deciduous Woodland adjacent to the South Western corner of the site.

Highways Information

Access: Maybe

Connectivity: Poor

Access comments: The land is a lot higher than the road. Best visibility is towards the bottom of the hill, just north of the access to the village hall. Conclusion: There are some issues with this site.

Landscape Information

Description: The site is a grass pasture field, sloping towards the south. Hedgerow boundaries are well maintained. Access from the road on the eastern boundary of the site (just to the north of the existing housing). The north east boundary is elevated above the adjacent road. The Landscape Character type is Plateau Estatelands. PRoW footpath PD5 crosses the centre of the site in an east to west direction.

Capacity: Moderate to High capacity.

Mitigation: PRoW footpath being redirected? Existing hedgerows need restoring and enhancing. Any loss of existing hedgerow would need appropriate compensation.

Site appraisal on next page...

De	livera	hi	litv
	IVCIA		ΠLY

Is the site suitable for development?		Is de	velopmen	t of the s	ite achievable?	Is the site available for development?		
✓ Yes	□ No	□ Partly		✓ Yes	□ No	□ Partly	✓ □ □ Yes No Don't know	
What is the	potential	timescale for dev	elopment of this site?					
1-5 years		6-10 years	6-10 years		11-15 years	Not in current plan period		
Potential site capacity 3								
Potential of	f the site	coming forwar	d for development					

Probability	Medium potential			
-------------	------------------	--	--	--

Justification

There is potential for development on this site, subject to the resolution of the constraining difference in height from the road. In landscape terms, there is a moderate to high capacity. The site has planning permission for 3 dwellings close to roadside, there may be scope for further development but this is dependent on reassessment (180117).

Basic Information							
Source	LA officer identified	Site Area (ha)	1	Greenfield/Brownfield?	✓ Greenfield □ Brownfield	Agricultural Land Classification	3

Technical Assessment

Flood Risk

Zone 1- Development is appropriate. A flood risk assessment will be required for sites greater than 1 ha in size. Nearby ordinary water courses and other sources of flooding, such as surface water flooding, should be explored for potential flood risk.

Water Information

Operator(s): Dwr Cymru Welsh Water (WS) Water Supply: Welsh Water will provide comment as part of the Rural Areas Site Allocation Development Plan Document consultation. Wastewater Treatment Works: Not known- private sewer

Biodiversity Information

Woodpasture and Parkland BAP priority habitat across the southern boundary roadside. Decidous woodland on the other side of the north east boundary.

Highways Information

Access: Maybe

Connectivity: Poor

Access comments: Best access would be off the road to the village hall. The corner and the proximity of farm buildings make access to the other road difficult. Conclusion: There are some issues with this site.

Landscape Information

Description: Part of the site features agricultural buildings, with the western and northern parts formed of grass pasture field, sloping towards the west and north. There is a good hedgerow boundary on the west and south of the site, with native trees. The Landscape Character type is Plateau Estatelands. Pudleston Court Unregistered Park and Garden is approx 20m to the south of the southern boundary. The Church of Saint Peter, a Grade II* Listed Building, is approx 80m to the south east. Visually, the site is well contained, especially from the east.

Capacity: Medium to high capacity. Especially the part with existing agricultural buildings on the eastern side of the site.

Mitigation: Hedgerows to be restored and enhanced. Proposed native trees and hedgerow planting on the northern and southern boundary.

Site appraisal on next page...

he site suitable	for development?	Is develo	pment of the s	site achievable?	Is the site available for developmen		
✓ □ Yes No	□ Partly	Ye	es No	□ Partly	□ □ ✓ Yes No Don't know		
at is the potenti	al timescale for develo	opment of this site?					
1-5 years 6-10		6-10 years		11-15 years	Not in current plan period		
tential site capad	city 8						

Justification

There is potential for development, particularly where the buildings are to the east. The best access would be off the road to the village hall. At present, there is no knowledge of it's availability.

Basic Information							
Dasic II	normation				Greenfield		
Source	LA officer	Site Area (ha)	0.67	Greenfield/Brownfield?	Brownfield	Agricultural Land Classification	3
	identified						

Technical Assessment

Flood Risk

Zone 1- Development is appropriate. A flood risk assessment will be required for sites greater than 1 ha in size. Nearby ordinary water courses and other sources of flooding, such as surface water flooding, should be explored for potential flood risk.

Water Information

Operator(s): Dwr Cymru Welsh Water (WS) Water Supply: Welsh Water will provide comment as part of the Rural Areas Site Allocation Development Plan Document consultation. Wastewater Treatment Works: Not known- private sewer

Biodiversity Information

Habitat of Principal Importance- Deciduous woodland on the other side of the road on the southern boundary, and beyond the site boundary in the west. Woodpasture and Parkland across the road from the southern boundary.

Highways Information

Access: Yes Connectivity: Poor Access comments: Visibility is good, but access is to a very narrow section of road. Conclusion: There are some issues with this site.

Landscape Information

Description: A grass pasture field, gently sloping towards the east. Hedgerows on northern and eastern boundary. The site is open and wet on the south east boundary. The Landscape Character type is Plateau Estatelands. Pudleston Court Unregistered Park and Garden is approx 100m to the south of the southern boundary. The Church of Saint Peter, a Grade II* Listed Building, is approx 80m to the south east. The land is open, with no boundary on the western side. It has a rural character. There is a potential visual connection with Pudlestone Court Garden. From the Village Hall looking south, there are open views of the site. Capacity: Low capacity

Site appraisal on next page...

Deliverability					
Is the site suitable for development?	Is development of th	e site achievable?	Is the site available for development?		
□ ✓ □ Yes No Partly	□ ✓ Yes No	□ Partly	☐		
What is the potential timescale for developm	ent of this site?				
1-5 years	6-10 years	11-15 years	Not in current plan period		
Potential site capacity 0					
Potential of the site coming forward for d	levelopment				

Probability No potential

Justification

The site is open and has more of a rural character, with views from the village hall and no clear visual boundary on the western side. It is not considered to be a suitable site for landscape reasons. At present, there is no evidence of availability.