

Basic Information									
Source Call for sites	Site Area (ha)	1 15	Greenfield/Brownfield?	Greenfield	Agricultural Land Classification	2			
Source Call for sites	Sile Alea (ila)	1.15	Greenneid/Drownneid?	Brownfield					

Technical Assessment

Flood Risk

Zone 3- The southern boundary of the site is in zone 3. An Exception Test, in accordance with paragraphs 159-161 of the NPPF, would be required.

Water Information

Operator(s): Dwr Cymru Welsh Water- will provide comment as part of the Rural Areas Site Allocation Development Plan Document consultation.

Biodiversity Information

Habitat of Principal Importance: Deciduous Woodland covering a significant area of the site.

Highways Information

Access: Maybe

Connectivity: Reasonable

Access comments: Very poor visibility at the junction between the lane access and B4348 main road. The access is prone to flooding. There is insufficient land either side to provide adequate visibility without 3rd party land.

Possible mitigation: Improve drainage in the area. Better access and connectivity from the private track to the north.

Conclusion: There are major issues with this site.

Landscape Information

Description: Comprises a strip of land at edge of settlement, located off C1262, within the Conservation Area. The site is crossed by a watercourse; The Gamber. It features linear vegetation along the watercourse. The northern section of the site is heavily vegetated. The Landscape Character Type is Sandstone Farmlands. Its in an edge of settlement location, part of the rural setting of church.

Capacity: Capacity is low/medium, for 1 to 2 dwellings on the south side of the watercourse.

Mitigation: Retention of existing vegetation to limit visual effects. Use of existing entrance.

Site appraisal on next page...

Deliverabilit	t y								
Is the site suitable for development?			nt? Is	developmer	nt of the s	ite achievable?	Is the site available for development?		
□ Yes	⊻ No	□ Partly		□ Yes	√ No	□ Partly	✓ □ □ Yes No Don't know		
What is the p	otential	timescale fo	r development of this site?	,					
1-5 years			6-10 years			11-15 years	Not in current plan period		
Potential site capacity 0									
Potential of	the site	coming for	ward for development						
Probability	No pot	ential							

Justification

The southern boundary of the site is in flood zone 3, and landscape impacts limit any capacity for development to the southern area. A significant proportion of the site is a Deciduous Woodland Priority Habitat. There are also major issues with access, therefore the site is wholly unsuitable.

Settlement Llanwarne Site Reference O/Llanw/001 Site Address Land West of Leniston Lane/ Gibraltar Post Code HR2 8JE Lane

Basic In	formation				_		
Source	LA officer	Site Area (ha)	0.97	Greenfield/Brownfield?	Greenfield	Agricultural Land Classification	2
oource	identified		0.07	Greenneid/Brownneid :	Brownfield		

Technical Assessment

Flood Risk

Zone 1- Development is appropriate. A flood risk assessment will be required for sites greater than 1 ha in size. Nearby ordinary water courses and other sources of flooding, such as surface water flooding, should be explored for potential flood risk.

Water Information

Operator(s): Dwr Cymru Welsh Water (WS) Water Supply: Welsh Water will provide comment as part of the Rural Areas Site Allocation Development Plan Document consultation. Wastewater Treatment Works: Not known- private sewer

Biodiversity Information

No protected species or statutory habitats are recorded at this location.

Highways Information

Access: Maybe Connectivity: Reasonable Access comments: Access from lanes to B4348 road is very poor and potentially dangerous. No visibility. PROW LW4 along southern boundary. Possible mitigation: Widen the lane as it is currently extremely narrow. Conclusion: There are major issues with this site.

Landscape Information

Description: Comprises a strip of pasture running parallel with Leniston Lane, with a gentle south facing slope. There is a roadside hedgerow with escaped trees. In an edge of settlement location.

Capacity: Medium Capacity - existing dwellings on the eastern side of Leniston Lane provide some context.

Mitigation: Retain the eastern boundary hedgerow. Introduce hedgerow along the remaining boundaries. Should be single storey dwellings to match existing

Site appraisal on next page...

Settlement	Llanw	arne	Site Reference	O/Llanw/001	Site	e Address	Land West of Len Lane	iston Lane/ Gibraltar	Post C	ode HR2 8JE
Deliverabili	ty									
Is the site su	iitable f	or developn	nent?	Is dev	elopmen	t of the site	e achievable?	Is the site ava	ailable fo	r development?
	✓					✓				✓
Yes	No	Partly			Yes	No	Partly	Yes	No	Don't know
What is the	potentia	I timescale	for development of	this site?						
									✓	
1-5 years 6-10		0 years			11-15 years	Not in curr	ent plan	period		
Potential site	e capac	ity 0								
Potential of	the sit	e coming f	orward for develo	pment						
Probability	No po	otential								

Justification

Moderate capacity in landscape terms, but there are currently major issues to overcome with access due to the narrowness of the lanes from the main road. There is little scope of improving this without affecting the village character. At present, there is no knowledge of availability.

Basic Information										
	officer	Site Area (ha)	1.53	Greenfield/Brownfield?	Greenfield Brownfield	Agricultural Land Classification	1			

Technical Assessment

Flood Risk

Zone 1- Development is appropriate. A flood risk assessment will be required for sites greater than 1 ha in size. Nearby ordinary water courses and other sources of flooding, such as surface water flooding, should be explored for potential flood risk.

Water Information

Operator(s): Dwr Cymru Welsh Water (WS) Water Supply: Welsh Water will provide comment as part of the Rural Areas Site Allocation Development Plan Document consultation. Wastewater Treatment Works: Not known- private sewer

Biodiversity Information

No protected species or statutory habitats are recorded at this location.

Highways Information

Access: Maybe Connectivity: Reasonable Access comments: Very poor visibility at the junction between the lane access and main road, B4348. Slightly outside of the village. Possible mitigation: Widen the lane along site frontage and improve visibility to B road. Conclusion: There are major issues with this site.

Landscape Information

Description: Comprises part of a larger arable field with rolling landform and boundary hedgerow. The ground level of the field is 2m higher than the roadside. The Landscape Character Type is Sandstone Farmlands. An arbitrary boundary line is drawn. Capacity: Medium. Some capacity for a small cluster of dwellings that relate to the settlement. Mitigation: Use of a landscape buffer to mitigate potential wider views. Change in level from road to site would need to be addressed.

Site appraisal on next page...

Deliverability												
Is the site suitable for development?					evelopmen	t of the s	ite achievable?	ls ti	Is the site available for development?			
□ Yes	✓ No	□ Partly			□ Yes	✓ No	□ Partly		□ Yes	□ No	☑ Don't know	
What is the	What is the potential timescale for development of this site?											
										✓		
1-5 years 6-10 year			6-10 years			11-15 years Not in current plan		ent plan	period			
Potential sit	te capaci	ty	0									
Potential of the site coming forward for development												

Probability No potential

Justification

The site is located on the outskirts of the village and is more open countryside in nature. There are major constraints to achieving access to this site and it is at a different level to the road. At present, there is no knowledge of its availability. The site is considered to have no potential.