Settlement Name Richa	ard's	Castle
-----------------------	-------	--------

Site Ref HLAA/034/001

Site Address Land to west of 4 Rosedale Cottages

Information Source Call for sites

Site Area (ha) 0.21 Potential Housing _{N/A} Capacity	Greenfield ☑ Brownfield □	Agricultural Land Classification ³
Is the site suitable for development?	Is development achievable on the site?	Is the site available?
Yes 🗌	Yes	Yes 🔽
No 🔽	No 🔽	No 🗆
Part	Part	Don't Know
Possible timescale for devel	opment?	
1-5 Years	11-15 Years 🛛	lot In Current Plan Period ☑
6-10 Years	16-20 Years	

Flood information

Zone 1 - Development is appropriate. A flood risk assessment will be required for sites greater than 1 Ha. Nearby ordinary watercourses and other sources of flooding such as surface water flooding should be explored for potential flood risk.

Water information

DCWW water supply infrastructure only. Waste water & treatment –spare capacity

Biodiversity information

UK BAP Priority Habitat (Habitat of Principal Importance)- Traditional Orchard

Highways information

Comments: Visibility bad to 'A' road; not recommended.

Possible mitigation: Needs third party land.

Site Address Land to west of 4 Rosedale Cottages

Information Source Call for sites

Landscape and Historic Environment information

Landscape Sensitivity: High - Moderate Landscape Capacity: Low - Moderate

Sensitivity & Capacity Analysis: The site is an old orchard, an important local feature, and part of village's historic character, with high potential for biodiversity. The site is inappropriate for development.

Site probability

No potential

Justification

The site is traditional orchard which is a BAP Habitat of Principal Importance. This is an important local feature and part of village's historic character. Access has poor visibility and is altogether inappropriate for development.

Site Address Land north of Springfield

Information Source LA officer identified

Site Area (ha) 0.47 Potential Housing _{N/A} Capacity	Greenfield Brownfield	 Agricultural Land Classification
Is the site suitable for development?	Is development achievable on the sit	Is the site available? e?
Yes 🗆	Yes 🗌	Yes 🗌
No 🗹	No 🔽	No 🗆
Part 🗌	Part	Don't Know 🔽
Possible timescale for develo	opment?	
1-5 Years	11-15 Years	Not In Current Plan Period 🔽
6-10 Years 🛛	16-20 Years	

Flood information

Zone 1 - Development is appropriate. A flood risk assessment will be required for sites greater than 1 Ha. Nearby ordinary watercourses and other sources of flooding such as surface water flooding should be explored for potential flood risk.

Water information

DCWW water supply infrastructure only. Waste water & treatment –spare capacity

Biodiversity information

No protected species or statutory habitats recorded at this location.

Highways information

Comments: Good visibility, best site in highways terms.

Site Address Land north of Springfield

Landscape and Historic Environment information

Landscape Sensitivity: High - Moderate Landscape Capacity: Low - Moderate

Sensitivity & Capacity Analysis: The site is in open countryside, forming an important part of the village's rural setting from the North and provides a clear edge to the built form. Development would be inappropriate, although the effects would probably be no more than locally significant.

Site probability

No potential

Justification

Site forms an important part of village's rural setting from north. Development inappropriate in this location.

Site Address Land to east of Westbrook

Information Source LA officer identified

Site Area (ha) 0.25 Potential Housing _{N/A} Capacity	Greenfield Brownfield	 ✓ Agricultural Land Classification 	
Is the site suitable for development?	Is development achievable on the site	Is the site available?	
Yes 🗌	Yes	Yes 🗌	
No 🗹	No 🔽	No	
Part 🗌	Part	Don't Know 🗹	
Possible timescale for development?			
1-5 Years	11-15 Years	Not In Current Plan Period	
6-10 Years 🛛	16-20 Years		

Flood information

Zone 1 - Development is appropriate. A flood risk assessment will be required for sites greater than 1 Ha. Nearby ordinary watercourses and other sources of flooding such as surface water flooding should be explored for potential flood risk.

Water information

DCWW water supply infrastructure only. Waste water & treatment –spare capacity

Biodiversity information

No protected species or statutory habitats recorded at this location.

Highways information

Comments: Visibility good. Good opportunity to improve missing footway.

Site Address Land to east of Westbrook

Information Source LA officer identified

Landscape and Historic Environment information

Landscape Sensitivity: High - Moderate Landscape Capacity: Low - Moderate

Sensitivity & Capacity Analysis: The site is in a sensitive, but not prominent, location at the gateway to the village. It has a relatively limited visual envelope. It may be possible to accommodate a single dwelling on a small parcel South of the watercourse.

Site probability

No potential

Justification

Site is in a sensitive gateway location where a single dwelling may be possible as there is a watercourse through the site. Due to inadequate capacity potential, it is not a suitable SHLAA site.

Site Address Land south of Methodist Church

Information Source LA officer identified

Site Area (ha) 0.26	Greenfield	✓ Agricultural Land
Potential Housing _{N/A} Capacity	Brownfield	Classification 3
Is the site suitable	Is development achievable on the site	Is the site available?
for development?	achievable on the site	er
Yes 🗆	Yes 🗌	Yes 🗆
No 🔽	No 🔽	No 🗆
Part 🗆	Part	Don't Know 🔽
Possible timescale for develo	opment?	
1-5 Years	11-15 Years	Not In Current Plan Period
6-10 Years	16-20 Years	

Flood information

Zone 1 - Development is appropriate. A flood risk assessment will be required for sites greater than 1 Ha. Nearby ordinary watercourses and other sources of flooding such as surface water flooding should be explored for potential flood risk.

Water information

DCWW water supply infrastructure only. Waste water & treatment –spare capacity

Biodiversity information

No protected species or statutory habitats recorded at this location.

Highways information

Comments: Visibility just satisfactory. A footway on 'A' road would be needed.

Site Address Land south of Methodist Church

Information Source LA officer identified

Landscape and Historic Environment information

Landscape Sensitivity: Moderate - High Landscape Capacity: Small parcel to North = Moderate Moderate

Field to South & West = Low -

Sensitivity & Capacity Analysis: The site is on the edge of good quality open countryside. It has a relatively limited visual envelope. There is potential for a small-scale development on the smaller parcel, but in the field it would unacceptably extend development into the countryside.

Site probability

No potential

Justification

Given the poor access and problems with visibility the site is unsuitable. Otherwise a site that could potentially accommodate small scale development only.

Site Address The Paddocks

Information Source LA officer identified

Site Area (ha) 0.29 Potential Housing _{N/A} Capacity	Greenfield Brownfield	✓ Agricultural Land Classification 3
Is the site suitable for development?	Is development achievable on the site	Is the site available?
Yes 🗌	Yes 🗌	Yes 🗌
No 🔽	No 🔽	No 🗌
Part 🗌	Part	Don't Know 🔽
Possible timescale for develo	pment?	
1-5 Years	11-15 Years	Not In Current Plan Period 🔽
6-10 Years	16-20 Years	

Flood information

Zone 1 - Development is appropriate. A flood risk assessment will be required for sites greater than 1 Ha. Nearby ordinary watercourses and other sources of flooding such as surface water flooding should be explored for potential flood risk.

Water information

DCWW water supply infrastructure only. Waste water & treatment –spare capacity

Biodiversity information

No protected species or statutory habitats recorded at this location.

Highways information

Comments: Visiblity bad to 'A' road; not recommended.

Possible mitigation: Needs third party land

Site Address The Paddocks

Landscape and Historic Environment information

Landscape Sensitivity: Moderate - Low Landscape Capacity: Moderate - High

Sensitivity & Capacity Analysis: There are some constraints to development. There are three Tree Preservation Orders on the Northern boundary of the site, but it has a very tight visual envelope (reliant on vegetation only in parts). There is potential for development if access is feasible (narrow track to existing property) and the vegetation is retained and protected (or if lost, mitigated for in long term).

Site probability

No potential

Justification

Due to a narrow track leading to the site, the visibility is poor and the site is therefore not recommended for development.

Site Address Land to south of Bank House

Information Source LA officer identified

Site Area (ha) 0.28 Potential Housing _{N/A} Capacity	Greenfield □ Brownfield ☑	Agricultural Land Classification ³
Is the site suitable for development?	Is development achievable on the site?	Is the site available?
Yes 🗌	Yes 🗌	Yes 🗌
No 🔽	No 🔽	No 🗌
Part	Part	Don't Know 🔽
Possible timescale for dev	velopment?	
1-5 Years	11-15 Years	Not In Current Plan Period 🛛 🔽
6-10 Years	16-20 Years	

Flood information

Zone 1 - Development is appropriate. A flood risk assessment will be required for sites greater than 1 Ha. Nearby ordinary watercourses and other sources of flooding such as surface water flooding should be explored for potential flood risk.

Water information

DCWW water supply infrastructure only. Waste water & treatment –spare capacity

Biodiversity information

No protected species or statutory habitats recorded at this location.

Highways information

Comments: Bad visibility to right, access not recommended.

Site Address Land to south of Bank House

Landscape and Historic Environment information

Landscape Sensitivity: Moderate - Low Landscape Capacity: Moderate

Sensitivity & Capacity Analysis: The visual envelope of the site is limited by the local topography, vegetation and built form. The site is associated with the existing settlement pattern. Given the built development context and apparent lack of constraints, the site could potentially accommodate new houses with limited adverse effects on the landscape and villagescape.

Site probability

No potential

Justification

Given the poor site access and problems with right side visibility, the site is unsuitable. Otherwise a site that could potentially accommodate new houses with limited adverse effects on land and villagescape.

Site Address Land north of Tan Brook

Information Source LA officer identified

Site Area (ha) 0.28 Potential Housing ₆ Capacity	Greenfield	Agricultural Land Classification 2
Is the site suitable for development?	Is development achievable on the site?	Is the site available?
Yes 🔽	Yes 🔽	Yes 🗌
No 🗌	No 🗆	No 🗆
Part	Part	Don't Know 🔽
Possible timescale for deve	lopment?	
1-5 Years	11-15 Years 🛛	Not In Current Plan Period
6-10 Years 🔽	16-20 Years □	

Flood information

Zone 1 - Development is appropriate. A flood risk assessment will be required for sites greater than 1 Ha. Nearby ordinary watercourses and other sources of flooding such as surface water flooding should be explored for potential flood risk.

Water information

DCWW water supply infrastructure only. Waste water & treatment –spare capacity

Biodiversity information

No protected species or statutory habitats recorded at this location.

Highways information

Comments: Visibility satisfactory. Footway needed on 'A' road.

Site Address Land north of Tan Brook

Information Source LA officer identified

Landscape and Historic Environment information

Landscape Sensitivity: High - Moderate Landscape Capacity: Moderate

Sensitivity & Capacity Analysis: The site is in the open countryside at a gateway location into the village from the North. It defines the character, context and setting but with otherwise limited visibility. There may be limited potential for well-designed, low-density houses.

Site probability

Medium potential

Justification

There is potential for a small scale residential development in this location. Any scheme should be welldesigned, low-density houses if footway on 'A' road can be provided.

