HEREFORDSHIRE PUBLIC REALM CONTRACT 2025/26

ANNEX 14 – STRUCTURES



ANNUAL PLAN FINAL APPROVAL

- BBLP: Chris Allen
- HC: Bruce Evans

SERVICE OVERVIEW

SERVICE SUMMARY

Highway Structures covered by the activities of this annex are defined in the national Structures Asset Valuation and Investment Tool (SAVI). This annex makes provision for the management and maintenance of Herefordhire Councils (HC) bridges and other structures and the provision of technical advice to support network management services such as adoptions of new assets, management of abnormal loads, the regulation of private highway structures, dealing with emergencies relating to highway structures, working in conjunction with other statutory asset owners (such as Utilities, Network Rail and Rail Residuary Board) and managing substandard structures.

Inspections of structures will be undertaken in accordance with National guidance. For every year, this equates to circa 600 inspections across the county. Further details of these inspections have been included in Appendix D. A forward programme will be continually maintained of defects and associated actions, which as at the time of writing this exceeds £28m. Works from this forward programme of identified works are prioritised in accordance with the principles outlined in the Structures Life Cycle Plan (LCP).

Higher benefit-cost preventative maintenance will be used where possible, however budgetary constraints and asset condition is likely to mean that reactive maintenance is likely to take higher priority. All structures works are considered against the inevitable balance between the disruption during the delivery of maintenance works and maintaining network resilience.

COMMISSIONED WORKS

The annex shall deliver all activities and works as set out in Schedule 4 – Service Information Annex 18 - Service Information Structures V1.4 unless deemed out of scope as detailed below.

THE SERVICE

SERVICE DELIVERY

SERVICE	RESOURCES	DIRECT/SUB CONTRACT	DELIVERY	COST 25-26
Capital Major Schemes (Schemes which exceed the parameters for the Minor Works Programme. This is evaluated on a case-by case basis).	Site Engineer + Construction/Project Management overseeing. Snr Engineer Input + Bridge	Direct/Sub-contract	Programmed	£450,000.00
Capital Minor Schemes (Generally works of short duration with minimal design input).	Maintenance Gang + Specialist Sub- contractors	Direct/Sub-contract	Programmed	£125,000.00

Balfour Beatty

Herefordshire Council

SERVICE	RESOURCES	DIRECT/SUB CONTRACT	DELIVERY	COST 25-26
Responding to In Year Identified Improvements Required to Highway Structures Minor improvements required to arrest deterioration or renew the components of highway structures. These schemes are specifically identified from inspections. This separate funding stream is established to reduce the impact on pre-identified planned works delivered through Capital Minor Structures.		Direct/Sub-contract	Programmed through the Year	£100,000.00
Principal Inspections for Structures	Snr. Bridge Engineer + Structures Inspector (2no.) + Engineer + Specialist Sub- contractor Snr. Bridge Engineer + Structures Inspector (2no.)	Direct	Programmed	£212,944.11
Structures Diving Inspections & Maintenance		Sub-contract	Programmed	£32,154.16
PROW Structure Inspection Inspection (only) of known large span and special Public Rights of Way bridges exceeding 7.5m.		Direct	Programmed	Included in the Principal Inspections Allowance
Structures General Inspections For the identification of capital improvement works.		Direct	Programmed	R £42,702.75 C £42,702.75
Safety Barrier Inspections Inspection of Vehicle Restraint Systems.		Direct/Sub-contract	Programmed	R £6,478.14 C £6,478.14

SERVICE	RESOURCES	DIRECT/SUB CONTRACT	DELIVERY	COST 25-26
Bridge Strike Support	Omitted as part of savings			
Development Control, Planning & Adoption, Network Management	Snr. Bridge Engineer + Structures Inspector (2no.)	tructures Inspector Direct		£24,850.29

SERVICE SCOPE

SERVICE	SCOPE
Highway Structures Specific Asset Management	 Service Scope Utilise a risk-based approach to select which structures can be inspected within funding constraints Manage the structures in accordance with HMEP asset management guidance Maintain and continue to enhance the AMX asset data records. Maintain a forward programme of known defects that have been scoped, risk assessed and prioritised. Development of an Annual Plan of capital schemes, from the forward programme of known defects. Provide technical advice on planning applications, note this is externally funded by Developers. Non-bridge HC owned structures, such as culverts and retaining walls come under the umbrella of 'other highway structures' and will be inspected, and managed through AMX in the same way as bridges. Provide assistance in arranging for other specialist inspections and maintenance for engineering works outside of 'The Baseline Specification for Highway Works – Public Realm Services'. Contribute to additional funding bids such as the challenge fund. Notes Specialist inspections and Bespoke asset management approach for highways structures other than Highway Bridges are not included.

SERVICE	SCOPE
Inspection and Maintenace of Highway Structures	 Service Scope Highway Safety Barriers Highway Bridges Highway Retaining Walls Bridges General Inspections to be undertaken every 2 years. Bridges Principal Inspections to be carried out generally every 6 years, but potential longer subject to agreement using a risk based approach. Bridge Management System to be updated within 1 Month following inspections and works being completed. The Inspection of PROW Structures where the Span exceeds 7.5m are undertaken under the provision of this annex. Public Rights of Way structures which are not on the current inventory but require inspection by the Structures Team will need to be reviewed by the PROW team prior to inclusion in the inspection regime. Notes The management and maintenance of Public Rights of Way Bridges (span less than 7.5m) are not included within this annex. Herefordshire Council Amenity Bridges are not included within this annex. Playgrounds, Non-retaining Walls, Buildings, Sculptures are not included within this annex.
Network Management	 Third party assets (other than safety inspections) Service Scope Technical liaison with the Network Management Team in the consenting, planning and supervision of Abnormal Loads on the county's highway network. Limited support for network infringements AIP Process as outlined in Appendices Liaison with Building Control Providing Technical review and Approval of Highway Structures in accordance with the AIP process, but funded by Developers (the cost associated with this service is estimated to be approximately £15,000 to £20,000 pa,) Notes There is limited support provisioned (based on previous years requirements) for dealing with network infringements Support and technical advice for issues that are the responsibility of Building Control are not part of the service scope. Unfunded Planning / Adoption Advice and support to HC Planning and adoption team. Assistance for the submission of AIP's and review of AIPs and granting TAA are not part of the service scope. The support of Developers or other third parties with design expertise is not part of the annex.

APPENDICES

APPENDIX A: BBLP POLICY & PROCESSES TO BE USED IN THE DELIVERY OF THE ANNEX

Balfour Beatty Group Minimum Engineering Expectations – Copy provided as appendix to service overview

Balfour Beatty Group Minimum Commercial Expectations – Copy provided as appendix to service overview

Balfour Beatty Project Management Best Practice Guide - Copy provided as appendix to service overview

Herefordshire Council Highway Maintenance Plan <u>Highway asset management and maintenance –</u> <u>Herefordshire Council</u>

Herefordshire Council Highways Development Guidance: Highway development – Herefordshire Council

APPENDIX B: PROGRAMME OF WORKS

The Programme of Works included within each element are as follows: Capital Major Schemes

SCHEME	ТҮРЕ	ΑCTIVITY	EASTING	NORTHING
Bredwardine Bridge	Repoint the structure to resolve motor loss defects	Access Platform or Scaffolding and repoint	333667	244729
Belmont Road	Feasibility and Design	Inspection for Assessment and Condition for repair and Repainting	350123	238710
Huntsham Bridge	Feasibility and Design	Detailed Design for Steel Repairs	356767	218150
Wilton Bridge	Feasibility and Design	Further investigation and design	358996	224212
Adforton Saddling	Construction Phase	Saddling works	340159	271070
Old School Lane Pipe Bridge	Establish options for bridge maintenance	Undertake Inspection for Assessment	351327	241654
Pontrilas Bridge	Feasibility and Design	Investigation and Design	339527	227548

Inspections of Highway Structures

Herefordshire Council Highways and Public Realm Contract

REFERENCE	NAME	INSPECTION TYPE	ASSET TYPE
BW7174	Crowards Mill Gabion	Principal Inspection	Retaining Wall
BW7258	Arrow Mill Wall	General Inspection	Retaining Wall
BR5005	Yarkhill Railway, Stoke Rd	Safety Inspection	Bridge
BW7182	Headbrook, Kington	General Inspection	Retaining Wall
BB0161	Eardisland	General Inspection	Bridge
BB0852	Field Culvert	General Inspection	Bridge
BF7664	Butterley Cottage	Safety Inspection	Bridge
FO2300059	Wigmore WQ6 2023	General Inspection	Bridge
BW7184	Bodenham Culvert Retaining Wall East	General Inspection	Retaining Wall
BW7169	Prospect Cottage, Kimbolton	Principal Inspection	Retaining Wall
BW7032	Old Road, Bromyard	Safety Inspection	Retaining Wall
BB0251	Petty	Principal Inspection	Bridge
BB0008	Bartestree	Principal Inspection	Bridge
BW7038	Back Brook, Kington	General Inspection	Retaining Wall
BB1296	Newtown Road Canal	General Inspection	Bridge
BB0271	Bullocks	Principal Inspection	Bridge
BW7257	Kington Bridge Wall	General Inspection	Retaining Wall
BW7259	Crooked Well Wall	General Inspection	Retaining Wall
BB0249	Lugg	Safety Inspection	Bridge
BF7763	Norton (Bromyard)	General Inspection	Bridge
BR5062	Bridge Inn Road Railway	Safety Inspection	Bridge
BR3627	Burcott Road Railway	Safety Inspection	Bridge
BW7039	Orleton Wall	Safety Inspection	Retaining Wall
BW7043	Firs Lane Bromyard	Safety Inspection	Retaining Wall
BW7195	Bodenham Culvert Retaining Wall West	General Inspection	Retaining Wall
BB0424	Hampton Mill	General Inspection	Bridge
BW7041	Hereford Rd Bromyard	Safety Inspection	Retaining Wall
BW7047	Millbrook St Hereford	General Inspection	Retaining Wall
BW7223	Instone	Safety Inspection	Retaining Wall
BW7030	Bromyard Hospital, Highwell Lane	General Inspection	Retaining Wall
BB0339	Limebrook Irish Bridge	General Inspection	Bridge
BB0113	Eign Street Subway	General Inspection	Bridge
BW7044	Church Lane Upper Sapey	Principal Inspection	Retaining Wall
BW7214	Hatfield	Safety Inspection	Retaining Wall
BW7281	A44 Victoria Close, Bromyard	Safety Inspection	Retaining Wall
BR3626	Eign Road Railway	Safety Inspection	Bridge
BW7215	Stoke Prior	Safety Inspection	Retaining Wall
BP7901	Castle Downton	Safety Inspection	Bridge
BW7048	Oldfields Close Leominster	Safety Inspection	Retaining Wall

REFERENCE	NAME	INSPECTION TYPE	ASSET TYPE
BW7035	Mill Street, Leominster	General Inspection	Retaining Wall
BB0050	Waterloo Mill Race	Principal Inspection	Bridge
BW7221	Linley Green (NOT Visible)	Safety Inspection	Retaining Wall
BF7917	Bodenham	Safety Inspection	Bridge
BF7803	Foy Suspension	Safety Inspection	Bridge
BF7804	Sellack	Safety Inspection	Bridge
BR5001	Eau-Withington Railway	Safety Inspection	Bridge
BW 7921	Lyde Gabions 2018	Safety Inspection	Retaining Wall
BF7521	Edvin Loach FB - EL6	Principal Inspection	Bridge
BB0691	Old Furnace	Safety Inspection	Bridge
BW7045	Rosemary Leintwardine	Safety Inspection	Retaining Wall
BB0164	Stone	Safety Inspection	Bridge
BP1074	Russian Cottage	Safety Inspection	Bridge
BF7911	Mousenatch	Safety Inspection	Bridge
BB0495	Lugwardine Flats Flood Arch No.10	Principal Inspection	Bridge
BB0166	Commercial Road Culvert	General Inspection	Bridge
BB1231	Orchard Gardens	General Inspection	Bridge
BB1080	Broxwood	General Inspection	Bridge
BB2722	Batchelors	Safety Inspection	Bridge
BB1016	Orleton Ford	General Inspection	Bridge
BB0487	Lugwardine Flats Flood Arch No.2	Principal Inspection	Bridge
BB0557	Lugg Mills Flood Arch No.6 EA Blocked	General Inspection	Bridge
BB0556	Lugg Mills Flood Arch No.5 EA Blocked Up	General Inspection	Bridge
BF7765	Sapey Mill	General Inspection	Bridge
BB0413	Rowe Culvert	General Inspection	Bridge
BB0100	Moor	General Inspection	Bridge
BB0093	lvington	Principal Inspection	Bridge
BB0403	Leintwardine Culvert	General Inspection	Bridge
BB0671	Wergin's Flood Arch No.3	General Inspection	Bridge
BB1025	Miltons Cross Culvert No.6	General Inspection	Bridge
BF7909	Kennels	General Inspection	Bridge
BB0533	Buckton Mill	General Inspection	Bridge
BF7770	The Batches	General Inspection	Bridge
BF7931	Knill	General Inspection	Bridge
BB0231	Noke Culvert No.1	General Inspection	Bridge
BB0929	Brockhall	General Inspection	Bridge
BB0078	Gosford	General Inspection	Bridge
BB0720	Poswick Culvert	General Inspection	Bridge
BF7919	Ivington Common	Principal Inspection	Bridge
BB0082	Mortimers Cross	Principal Inspection	Bridge

REFERENCE	NAME	INSPECTION TYPE	ASSET TYPE
BF7926	Shobdon Marsh	General Inspection	Bridge
BB0478	Eardisland Mill	General Inspection	Bridge
BB0058	Risbury	General Inspection	Bridge
BR5080	Sunset Kington	Safety Inspection	Bridge
BB0798	Marshfield Culvert (Saddled)	General Inspection	Bridge
BF7937	Main Ditch Kimbolton	General Inspection	Bridge
BB2825	High Bridge	Safety Inspection	Bridge
BB0462	Almeley Culvert No.1	General Inspection	Bridge
BB0223	Dilwyn Underpass	General Inspection	Bridge
BB0236	Staunton Culvert	General Inspection	Bridge
BB0373	Aymestrey bridge	Principal Inspection	Bridge
BB0444	Hatfield	General Inspection	Bridge
BB0619	Lugg Mills Flood Arch No.8 EA Blocked Up	General Inspection	Bridge
BB0554	Limebrook	General Inspection	Bridge
BB0206	Upcott	General Inspection	Bridge
BB1103	Wicton	General Inspection	Bridge
BB0211	Headbrook (Saddled)	General Inspection	Bridge
BB0597	Lower House	General Inspection	Bridge
BB0860	Logaston	General Inspection	Bridge
BF7771	Cheaton Brook	General Inspection	Bridge
BB0924	Hyde Farm	General Inspection	Bridge
BB0451	Oakley Mill	General Inspection	Bridge
BB0103	Calderwell	General Inspection	Bridge
BB0692	Bidney	General Inspection	Bridge
BB0479	Red Lake	General Inspection	Bridge
BB0501	Westbrook	General Inspection	Bridge
BB0423	Paunton	General Inspection	Bridge
BB1295	Southern Avenue Bridge	General Inspection	Bridge
BB0565	Monkland Culvert	General Inspection	Bridge
BB0669	Wergin's Flood Arch No.1	General Inspection	Bridge
BB0718	Poswick	General Inspection	Bridge
BB0491	Lugwardine Flats Flood Arch No.6	Principal Inspection	Bridge
BB0248	Hindwell Bridge	General Inspection	Bridge
BF7922	Limebrook	General Inspection	Bridge
BB0616	Lugg Mills Flood Arch No.1	General Inspection	Bridge
BB0063	Eye	General Inspection	Bridge
BB0612	Whitbourne Ford (Saddled)	General Inspection	Bridge
BF7913	Nash	General Inspection	Bridge
BB0085	Lugg Green	Principal Inspection	Bridge
BB0099	Cornett	General Inspection	Bridge
BB0456	Stockton Ford	General Inspection	Bridge

REFERENCE	NAME	INSPECTION TYPE	ASSET TYPE
BB0154	Knapton	General Inspection	Bridge
BB0927	Pudleston	General Inspection	Bridge
BB0932	Stocktonbury	General Inspection	Bridge
BB0186	College Road Canal Bridge	General Inspection	Bridge
BB0209	Mahollam	General Inspection	Bridge
BB0811	Lingen Castle	General Inspection	Bridge
BB0246	Combe	General Inspection	Bridge
BB0446	Tick	General Inspection	Bridge
BB0033	Back Brook	Principal Inspection	Bridge
BB0386	Lyepool	Principal Inspection	Bridge
BB0574	Locks	General Inspection	Bridge
BR5043	Leominster Railway	Safety Inspection	Bridge
BB2037	Sapey, Gaines	General Inspection	Bridge
BB0095	Ford Bridge	Principal Inspection	Bridge
BB0072	Little Hereford	General Inspection	Bridge
BB0976	Lower Lye Culvert	General Inspection	Bridge
BB0040	Brockmanton Culvert	General Inspection	Bridge
BR5050	Bredenbury Railway	Safety Inspection	Bridge
BB0485	Arrow Green Flood Arch	General Inspection	Bridge
BB0523	Criftinford Culvert	General Inspection	Bridge
BB0401	Adleymoor Culvert	Principal Inspection	Bridge
BB1107	Marden Memorial	General Inspection	Bridge
BB0840	Sodgley	General Inspection	Bridge
BB0009	Bartestree Culvert	Principal Inspection	Bridge
BB0214	Kington	General Inspection	Bridge
BB0598	Station	General Inspection	Bridge
BR5049	Fencote Railway	Safety Inspection	Bridge
BB0254	Wheatsheaf	General Inspection	Bridge
BB0741	Cemetery	General Inspection	Bridge
BB0215	Arrow Mill (Kington)	General Inspection	Bridge
BB0475	Holmcroft	General Inspection	Bridge
BB0240	Leen Culvert	General Inspection	Bridge
BR5003	Shucknall Hill, Bridge House	Safety Inspection	Bridge
BB0102	Brockington	General Inspection	Bridge
BB0160	Brooch	General Inspection	Bridge
BB0220	Westonbury	General Inspection	Bridge
BB0713	Moss Hill	General Inspection	Bridge
BB0528	Whyle Mill	General Inspection	Bridge
BB0591	New	General Inspection	Bridge
BB0088	Tollbar	General Inspection	Bridge
BB1188	Mill (Bullocks Mill)	General Inspection	Bridge
BF7520	Hatfield B/B	General Inspection	Bridge

ASSET TYPE REFERENCE NAME **INSPECTION TYPE** BB0147 Swan Inn Culvert General Inspection Bridge **BB0086** Waterlow General Inspection Bridge **BB0056** Eaton Principal Inspection Bridge BB0594 Hergest Culvert General Inspection Bridge Lugg Mills Flood Arch No.11 EA BB0621 General Inspection Bridge Blocked Up Lugg Mills Flood Arch No.7 EA Blocked BB0558 General Inspection Bridge Up BB0091 Owemer Principal Inspection Bridge BF7911 Mousenatch General Inspection Bridge Marston Culvert BB0819 General Inspection Bridge BB0256 **Boillets** General Inspection Bridge BF7935 Halls Mill No 2 General Inspection Bridge BB0244 **Ivinaton Court** General Inspection Bridge BB0371 Shobdon Culvert General Inspection Bridge **BB1136** Wyson Culvert General Inspection Bridge BF7929 Back Brook Kington General Inspection Bridge **BB0939** Rowden Mill General Inspection Bridge BB0258 Stoney General Inspection Bridge Bridge **BB0630** Longlands General Inspection Broadward Flood Arch No.2 **BB0608** General Inspection Bridge **BB0222** Pembridge General Inspection Bridge BF7908 Park Stile Mill General Inspection Bridge BB0277 **Berry Lane Culvert** General Inspection Bridge Little Lugg Principal Inspection BB0476 Bridge Noke Culvert No.2 General Inspection **BB0568** Bridge BB0426 Kinsham General Inspection Bridge BB0672 Wergin's Flood Arch No.4 General Inspection Bridge Newmarket Street Subway (FILLED IN **BB0168** Safety Inspection Bridge 2013) BB0014 Lea General Inspection Bridge BB0716 Cheese General Inspection Bridge **BB0412** Milton Culvert No.5 General Inspection Bridge BF7916 Little Hereford General Inspection Bridge BB0081 Eyton General Inspection Bridge BB0276 Kings Meadow Culvert General Inspection Bridge BB0145 New General Inspection Bridge **BB0500** Aston Culvert General Inspection Bridge BB1114 Offa's Dyke General Inspection Bridge BB0057 Steens General Inspection Bridge BB0527 Keephill General Inspection Bridge **BB0496** Lugwardine Flats Flood Arch No.11 Principal Inspection Bridge BB0943 Haybridge **General Inspection** Bridge

REFERENCE	NAME	INSPECTION TYPE	ASSET TYPE
BB0022	Marlbrook Railway	General Inspection	Bridge
BB0369	Leintwardine	General Inspection	Bridge
BB0670	Wergin's Flood Arch No.2	General Inspection	Bridge
BB0512	Lowbrook	General Inspection	Bridge
BB0210	Pentile	General Inspection	Bridge
BB0054	Ridgemoor	General Inspection	Bridge
BB0445	Hamnish	General Inspection	Bridge
BF7902	Twt No1	General Inspection	Bridge
BB1187	Lower Kimbolton	General Inspection	Bridge
BB0219	Rodd (Saddled 2002)	General Inspection	Bridge
BP5081	Floodgates Railway Kington	Safety Inspection	Bridge
BB0158	Sollers Dilwyn	General Inspection	Bridge
BB0522	Watling Street Culvert	General Inspection	Bridge
BB0164	Stone	General Inspection	Bridge
BB2823	Birchley Farm	Safety Inspection	Bridge
BB0488	Lugwardine Flats Flood Arch No.3	Principal Inspection	Bridge
BR5052	Bromyard	Safety Inspection	Bridge
BB0159	Tippets	General Inspection	Bridge
BB0031	Brockington Road	General Inspection	Bridge
BF7903	Mahollam Footbridge	General Inspection	Bridge
BB0890	The Meadows	General Inspection	Bridge
BF7907	Grove Farm	General Inspection	Bridge
BF7871	Swan Inn	General Inspection	Bridge
BB0232	Noke	General Inspection	Bridge
BF7917	Bodenham	Principal Inspection	Bridge
BB0162	Fields Place	General Inspection	Bridge
BB0011	Tupsley	Principal Inspection	Bridge
BF7869	Old School Lane	Principal Inspection	Bridge
BF7665	Avenbury	General Inspection	Bridge
BF7758	Norton also Newhouse Farm	General Inspection	Bridge
BB0156	Full	General Inspection	Bridge
BB0521	Locks Canal	General Inspection	Bridge
BB0390	Criftinford	Principal Inspection	Bridge
BB0013	Sutton Marsh Culvert	General Inspection	Bridge
BB0090	Monkland	Principal Inspection	Bridge
BF5115	Railway Industrial FB, Bromyard	General Inspection	Bridge
BB0609	Broadward Flood Arch No.3	General Inspection	Bridge
BB0201	Bower	General Inspection	Bridge
BB0388	Parsons Pole	General Inspection	Bridge
BB0059	Broadward	General Inspection	Bridge
BB0017	Moreton-On-Lugg Bridge	General Inspection	Bridge
BR5040	Horseway Head Railway	Safety Inspection	Bridge

REFERENCE	NAME	INSPECTION TYPE	ASSET TYPE
BB0087	Arrow Green	General Inspection	Bridge
BB0121	Bromyard Subway	General Inspection	Bridge
BB0693	Coxall	General Inspection	Bridge
BB0252	Broad	General Inspection	Bridge
BB0892	Saffrons Cross Culvert	General Inspection	Bridge
BB0827	The Willows	General Inspection	Bridge
BB0260	Noakes	General Inspection	Bridge
BB0015	Wergins	Principal Inspection	Bridge
BF7868	College Rd Hfd	General Inspection	Bridge
BB0893	Glebe Farm	General Inspection	Bridge
BB0261	Norton Edwin	General Inspection	Bridge
BB0224	Bullocks Mill	General Inspection	Bridge
BB0092	Crowmer	Principal Inspection	Bridge
BB0617	Lugg Mills Flood Arch No.2	General Inspection	Bridge
BB0915	Little Cowarne	General Inspection	Bridge
BB0497	Lugwardine Flats Flood Arch No.12	Principal Inspection	Bridge
BB0429	Hyde (Saddled)	General Inspection	Bridge
BB0607	Broadward Flood Arch No.1	General Inspection	Bridge
BB0668	Cobnash	General Inspection	Bridge
BB0652	Bodenham Culvert	General Inspection	Bridge
BB0084	Brook End	General Inspection	Bridge
BB0673	Wergin's Flood Arch No.5	General Inspection	Bridge
BB0101	Bodenham Bridge	General Inspection	Bridge
BB0253	Instone	General Inspection	Bridge
BB0931	Northeaton	General Inspection	Bridge
BB0477	Preston Wynne	General Inspection	Bridge
BB0542	Dunhampton	General Inspection	Bridge
BB0700	Burrington Flood Arch	General Inspection	Bridge
BB0596	Moreton (Saddled)	General Inspection	Bridge
BR5046	Wooferton Railway (not in Hereford)	Safety Inspection	Bridge
BB0578	Kenwater	General Inspection	Bridge
BB0391	Buckton	General Inspection	Bridge
BB0098	Hampton Court	Principal Inspection	Bridge
BB0089	Moorbrook	General Inspection	Bridge
BF7918	Priory (Kenwater)	General Inspection	Bridge
BB0163	Gadd	General Inspection	Bridge
BF7923	Highfield	General Inspection	Bridge
BB0511	Horseway Head	General Inspection	Bridge
BF7934	Knill Farm	General Inspection	Bridge
BB0824	The Kennels Culvert	General Inspection	Bridge
BB0213	Curlbrook	General Inspection	Bridge
BR5054	Humber Brook	Safety Inspection	Bridge

REFERENCE	NAME	INSPECTION TYPE	ASSET TYPE
BB0238	Cherrybrook Close Culvert	General Inspection	Bridge
BB0062	Luston	General Inspection	Bridge
BB0094	Honey Lake	Principal Inspection	Bridge
BB0457	Hawthorn	General Inspection	Bridge
BB0397	Brandon	General Inspection	Bridge
BB0492	Lugwardine Flood Arch	Principal Inspection	Bridge
BB0182	Widemarsh Brook Culvert	General Inspection	Bridge
BB0096	Marlbrook	General Inspection	Bridge
BB0593	Convent	General Inspection	Bridge
BB0387	Deerfold (or Darlings)	Principal Inspection	Bridge
BF7912	Mowley	General Inspection	Bridge
BF7920	Milking	Principal Inspection	Bridge
BB0376	Adforton (Div. Cul.)	General Inspection	Bridge
BB0076	Pembridge Station	General Inspection	Bridge
BB0005	Waterloo	General Inspection	Bridge
BB0155	Stretford	Principal Inspection	Bridge
BF7936	Clun	General Inspection	Bridge
BB0034	Arrow River	Principal Inspection	Bridge
BR5060	Commercial Road Railway	Safety Inspection	Bridge
BB0428	Pencombe Mill Culvert	General Inspection	Bridge
BB0507	Stockbridge	General Inspection	Bridge
BW7040	Barons Cross Road	General Inspection	Retaining Wall
BF7914	Burnt Hencoed	General Inspection	Bridge
BR5017	Beggard Railway (culvert)	Safety Inspection	Bridge
BB0481	Kinsham Cross Culvert	Safety Inspection	Bridge
BB1320	Lugwardine North Flood Arch No.1	Principal Inspection	Bridge
BB0195	Old Canal Bridge	Principal Inspection	Bridge
BR5053	Burley Railway	Safety Inspection	Bridge
BB1150	Mortimers Cross Culvert	Principal Inspection	Bridge
BB0010	Lugwardine Bridge	Principal Inspection	Bridge
BF7921	Jay Farm	General Inspection	Bridge
BB1066	Stapleton Castle	General Inspection	Bridge
BB0396	Brandon Culvert	General Inspection	Bridge
BB0858	Almeley Station	General Inspection	Bridge
BB0247	Combe Culvert	General Inspection	Bridge
BB0837	Yarpole	Principal Inspection	Bridge
BF7870	Walney Farm	General Inspection	Bridge
BF7928	Crooked Well	General Inspection	Bridge
BF7905	Field (New bridge to be updated)	General Inspection	Bridge
BB0812	Ongar Street Culvert	General Inspection	Bridge
BB0384	Birtley (Saddled 2024)	General Inspection	Bridge
BF7760	Little Cowarne	General Inspection	Bridge

BB0559 Lugg Mills Flood Arch No.10 General Inspection Bridge BB0153 Long General Inspection Bridge BB0229 Hunton Bridge General Inspection Bridge BB0212 Headbrook Culvert General Inspection Bridge BB0225 Leinthall Moor General Inspection Bridge BB0226 Leinthall Moor General Inspection Bridge BB0223 Little Arrow Principal Inspection Bridge BB0233 Noke Culvert No.5 General Inspection Bridge BB0233 Noke Flood Arch General Inspection Bridge BB0333 Oak (Railway) Safety Inspection Bridge BB041 Ridgeway Canal General Inspection Bridge BB0230 Moor Court General Inspection Bridge BB0243 Milbrook Street General Inspection Bridge BB02444 Eyecote General Inspection Bridge BB0449 Englands Gate General Inspection Bridge BB	REFERENCE	NAME	INSPECTION TYPE	ASSET TYPE
BB0229 Hunton Bridge General Inspection Bridge BB0473 Whitbourne Culvert General Inspection Bridge BB0212 Headbrook Culvert General Inspection Bridge BB7924 Westbrook General Inspection Bridge BB0235 Little Arrow Principal Inspection Bridge BB0233 Noke Culvert No.5 General Inspection Bridge BB0233 Noke Flood Arch General Inspection Bridge BR5041 Burcott Railway Safety Inspection Bridge BB0230 Oak (Railway) Safety Inspection Bridge BB0201 Ridgeway Canal General Inspection Bridge BB0203 Wells Culvert Principal Inspection Bridge BB0243 Milbrook Street General Inspection Bridge BB0216 Floodgates General Inspection Bridge BB0449 Englands Gate General Inspection Bridge BB0064 Eyecote General Inspection Bridge BB049	BB0559	Lugg Mills Flood Arch No.10	General Inspection	Bridge
BB0473 Whitbourne Culvert General Inspection Bridge BB0212 Headbrook Culvert General Inspection Bridge BF7924 Westbrook General Inspection Bridge BB0235 Little Arrow Principal Inspection Bridge BB0233 Noke Culvert No.5 General Inspection Bridge BB0233 Noke Culvert No.5 General Inspection Bridge BR5041 Burcott Railway Safety Inspection Bridge BB0230 Oak (Railway) Safety Inspection Bridge BB0280 Wells Culvert Principal Inspection Bridge BB0280 Moor Court General Inspection Bridge BB0243 Milbrook Street General Inspection Bridge BB0246 Englands Gate General Inspection Bridge BB0246 Elgocate General Inspection Bridge BB0246 Lugwardine Flats Flood Arch No.1 Principal Inspection Bridge BB0486 Lugwardine Flats Flood Arch No.9 Principal Inspection Bridge BB0486 Lugwardine Flats Flood Arch No.9 Principal Inspection Bridge BB0481 Alton General Inspection Bridge BB0383 Burini	BB0153	Long	General Inspection	Bridge
BB0212 Headbrook Culvert General Inspection Bridge BF7924 Westbrook General Inspection Bridge BB0826 Leinthall Moor General Inspection Bridge BB0235 Little Arrow Principal Inspection Bridge BB0233 Noke Flood Arch General Inspection Bridge BR5041 Burcott Railway Safety Inspection Bridge BR3603 Oak (Railway) Safety Inspection Bridge B80201 Ridgeway Canal General Inspection Bridge B802020 Wells Culvert Principal Inspection Bridge B80243 Millbrook Street General Inspection Bridge B80243 Millbrook Street General Inspection Bridge B80246 Eycote General Inspection Bridge B80449 Englands Gate General Inspection Bridge B80446 Lugwardine Flats Flood Arch No.9 Principal Inspection Bridge B80451 Alton General Inspection Bridge	BB0229	Hunton Bridge	General Inspection	Bridge
BF7924 Westbrook General Inspection Bridge BB0226 Leinthall Moor General Inspection Bridge BB0235 Little Arrow Principal Inspection Bridge BB0233 Noke Culvert No.5 General Inspection Bridge BB0233 Noke Flood Arch General Inspection Bridge BR5041 Burcott Railway Safety Inspection Bridge BR3003 Oak (Railway) Safety Inspection Bridge BB0280 Wells Culvert Principal Inspection Bridge BB0243 Millbrook Street General Inspection Bridge BB0243 Millbrook Street General Inspection Bridge BB0244 Englands Gate General Inspection Bridge BB0046 Lugwardine Flats Flood Arch No.1 Principal Inspection Bridge BB0486 Lugwardine Flats Flood Arch No.9 Principal Inspection Bridge BB0494 Lugwardine Flats Flood Arch No.9 Principal Inspection Bridge BB0517 Sunset General Inspection	BB0473	Whitbourne Culvert	General Inspection	Bridge
BB0826 Leinthall Moor General Inspection Bridge BB0235 Little Arrow Principal Inspection Bridge BB0233 Noke Culvert No.5 General Inspection Bridge BB0233 Noke Flood Arch General Inspection Bridge BR5041 Burcott Railway Safety Inspection Bridge BB0230 Oak (Railway) Safety Inspection Bridge BB0240 Wells Culvert Principal Inspection Bridge BB0240 Moor Court General Inspection Bridge BB0243 Millbrook Street General Inspection Bridge BB0244 Englands Gate General Inspection Bridge BB0216 Floodgates General Inspection Bridge BB0486 Lugwardine Flats Flood Arch No.1 Principal Inspection Bridge BB0416 Lugwardine Flats Flood Arch No.9 Principal Inspection Bridge BB0417 Sunset General Inspection Bridge BB0428 Lugwardine Flats Flood Arch No.9 Principal Inspection	BB0212	Headbrook Culvert	General Inspection	Bridge
BB0235Little ArrowPrincipal InspectionBridgeBB0239Noke Culvert No.5General InspectionBridgeBB0233Noke Flood ArchGeneral InspectionBridgeBR5041Burcott RailwaySafety InspectionBridgeBR3003Oak (Railway)Safety InspectionBridgeBB020Moor CourtGeneral InspectionBridgeBB0420Moor CourtGeneral InspectionBridgeBB0421Englands GateGeneral InspectionBridgeBB0424Millbrook StreetGeneral InspectionBridgeBB0449Englands GateGeneral InspectionBridgeBB0449Englands GateGeneral InspectionBridgeBB0449Englands GateGeneral InspectionBridgeBB0449Englands GateGeneral InspectionBridgeBB0644EyecoteGeneral InspectionBridgeBB0655LadymeadowGeneral InspectionBridgeBB0444Lugwardine Flats Flood Arch No.1Principal InspectionBridgeBB0451AltonGeneral InspectionBridgeBB045217SunsetGeneral InspectionBridgeBB0531AltonGeneral InspectionBridgeBB0543College Rd RailwaySafety InspectionBridgeBB0543College Rd RailwaySafety InspectionBridgeBB0543College Rd RailwaySafety InspectionBridgeBB0543College Rd RailwaySafety InspectionBridge	BF7924	Westbrook	General Inspection	Bridge
BB0239Noke Culvert No.5General InspectionBridgeBB0233Noke Flood ArchGeneral InspectionBridgeBR5041Burcott RailwaySafety InspectionBridgeBR3603Oak (Railway)Safety InspectionBridgeBB0801Ridgeway CanalGeneral InspectionBridgeBB0280Wells CulvertPrincipal InspectionBridgeBB0243Millbrook StreetGeneral InspectionBridgeBB0449Englands GateGeneral InspectionBridgeBB0449Englands GateGeneral InspectionBridgeBB0449Englands GateGeneral InspectionBridgeBB0449Englands GateGeneral InspectionBridgeBB0644EyecoteGeneral InspectionBridgeBB0445Lugwardine Flats Flood Arch No.1Principal InspectionBridgeBB0446Lugwardine Flats Flood Arch No.9Principal InspectionBridgeBB0451AltonGeneral InspectionBridgeBB0217SunsetGeneral InspectionBridgeBB0389BurringtonPrincipal InspectionBridgeBB0543College Rd RailwaySafety InspectionBridgeBB0444Kingsland MillGeneral InspectionBridgeBB0545College Rd RailwaySafety InspectionBridgeBB0545Gipsy HallGeneral InspectionBridgeBB0645Lugg Mills Flood Arch No.4General InspectionBridgeBB0705Gipsy HallGeneral I	BB0826	Leinthall Moor	General Inspection	Bridge
BB0233Noke Flood ArchGeneral InspectionBridgeBR5041Burcott RailwaySafety InspectionBridgeBR3603Oak (Railway)Safety InspectionBridgeBB0801Ridgeway CanalGeneral InspectionBridgeBB0280Wells CulvertPrincipal InspectionBridgeBB0243Millbrook StreetGeneral InspectionBridgeBB0243Millbrook StreetGeneral InspectionBridgeBB0244Englands GateGeneral InspectionBridgeBB0245FloodgatesGeneral InspectionBridgeBB0464EyecoteGeneral InspectionBridgeBB0455LadymeadowGeneral InspectionBridgeBB0464Lugwardine Flats Flood Arch No.1Principal InspectionBridgeBB0451AltonGeneral InspectionBridgeBB0217SunsetGeneral InspectionBridgeBB0218Kingsland MillGeneral InspectionBridgeBB0389BurringtonPrincipal InspectionBridgeBB0548Kingsland MillGeneral InspectionBridgeBB0563College Rd RailwaySafety InspectionBridgeBB0255Lugg Mills Flood Arch No.4General InspectionBridgeBB0306MarientudyGeneral InspectionBridgeBB0548Kingsland MillGeneral InspectionBridgeBB0563College Rd RailwaySafety InspectionBridgeBB0564Lugg Mills Flood Arch No.4General Inspection<	BB0235	Little Arrow	Principal Inspection	Bridge
BR5041Burcott RailwaySafety InspectionBridgeBR3603Oak (Railway)Safety InspectionBridgeBB0801Ridgeway CanalGeneral InspectionBridgeBB0280Wells CulvertPrincipal InspectionBridgeBB0220Moor CourtGeneral InspectionBridgeBB0243Millbrook StreetGeneral InspectionBridgeBB0449Englands GateGeneral InspectionBridgeBB0216FloodgatesGeneral InspectionBridgeBB0054EyecoteGeneral InspectionBridgeBB0486Lugwardine Flats Flood Arch No.1Principal InspectionBridgeBB0494Lugwardine Flats Flood Arch No.9Principal InspectionBridgeBB0495LadymeadowGeneral InspectionBridgeBB0494Lugwardine Flats Flood Arch No.9Principal InspectionBridgeBB0217SunsetGeneral InspectionBridgeBB0389BurringtonPrincipal InspectionBridgeBB0389BurringtonPrincipal InspectionBridgeBB0303StreffordburyGeneral InspectionBridgeBB0304College Rd RailwaySafety InspectionBridgeBB0305Lugg Mills Flood Arch No.4General InspectionBridgeBB0306StreffordburyGeneral InspectionBridgeBB0308BurringtonPrincipal InspectionBridgeBB0309JayGeneral InspectionBridgeBB04016Marsh CrossingPrin	BB0239	Noke Culvert No.5	General Inspection	Bridge
BR3603Oak (Railway)Safety InspectionBridgeBB0801Ridgeway CanalGeneral InspectionBridgeBB0280Wells CulvertPrincipal InspectionBridgeBB0820Moor CourtGeneral InspectionBridgeBB0434Millbrook StreetGeneral InspectionBridgeBB0449Englands GateGeneral InspectionBridgeBB0449Englands GateGeneral InspectionBridgeBB0446Lugwardine Flats Flood Arch No.1Principal InspectionBridgeBB0486Lugwardine Flats Flood Arch No.9Principal InspectionBridgeBB0494Lugwardine Flats Flood Arch No.9Principal InspectionBridgeBB0531AltonGeneral InspectionBridgeBB070Maidenhyde FarmGeneral InspectionBridgeBB0389BurringtonPrincipal InspectionBridgeBB0548Kingsland MillGeneral InspectionBridgeBB0250Gilege Rd RailwaySafety InspectionBridgeBB0303StreffordburyGeneral InspectionBridgeBB0304Mills Flood Arch No.4General InspectionBridgeBB02548Kingsland MillGeneral InspectionBridgeBB0255Lugg Mills Flood Arch No.4General InspectionBridgeBB0303StreffordburyGeneral InspectionBridgeBB0314MillGeneral InspectionBridgeBB0325Lugg Mills Flood Arch No.4General InspectionBridgeBB0365	BB0233	Noke Flood Arch	General Inspection	Bridge
BB0801Ridgeway CanalGeneral InspectionBridgeBB0280Wells CulvertPrincipal InspectionBridgeBB0820Moor CourtGeneral InspectionBridgeBB0243Millbrook StreetGeneral InspectionBridgeBB02449Englands GateGeneral InspectionBridgeBB0216FloodgatesGeneral InspectionBridgeBB0446Lugwardine Flats Flood Arch No.1Principal InspectionBridgeBB0451LadymeadowGeneral InspectionBridgeBB0454Lugwardine Flats Flood Arch No.9Principal InspectionBridgeBB0531AltonGeneral InspectionBridgeBB0531AltonGeneral InspectionBridgeBB0549Lugwardine Flats Flood Arch No.9Principal InspectionBridgeBB0531AltonGeneral InspectionBridgeBB0549BurringtonPrincipal InspectionBridgeBB0549BurringtonPrincipal InspectionBridgeBB0548Kingsland MillGeneral InspectionBridgeBB0543College Rd RailwaySafety InspectionBridgeBB0255Gipsy HallGeneral InspectionBridgeBB0366Marsh CrossingPrincipal InspectionBridgeBB0362Yearsett RailwaySafety InspectionBridgeBB0364Marsh CrossingPrincipal InspectionBridgeBB0365Lugg Mills Flood Arch No.4General InspectionBridgeBB0366Wergin's South Flood	BR5041	Burcott Railway	Safety Inspection	Bridge
BB0280Wells CulvertPrincipal InspectionBridgeBB0820Moor CourtGeneral InspectionBridgeBB0243Millbrook StreetGeneral InspectionBridgeBB02449Englands GateGeneral InspectionBridgeBB0216FloodgatesGeneral InspectionBridgeBB0486Lugwardine Flats Flood Arch No.1Principal InspectionBridgeBB0486Lugwardine Flats Flood Arch No.9Principal InspectionBridgeBB0494Lugwardine Flats Flood Arch No.9Principal InspectionBridgeBB0217SunsetGeneral InspectionBridgeBB0389BurringtonPrincipal InspectionBridgeBB0389BurringtonPrincipal InspectionBridgeBB0389BurringtonPrincipal InspectionBridgeBB0541AltonGeneral InspectionBridgeBB0389BurringtonPrincipal InspectionBridgeBB0542College Rd RailwaySafety InspectionBridgeBB0543College Rd RailwaySafety InspectionBridgeBB0544Marsh CrossingPrincipal InspectionBridgeBB0555Lugg Mills Flood Arch No.4General InspectionBridgeBB0562Wergin's South Flood Arch No.6General InspectionBridgeBB0555Lugg Mills Flood Arch No.6General InspectionBridgeBB0662Wergin's South Flood Arch No.6General InspectionBridgeBB0655Lugg Mills Flood Arch No.6General Inspectio	BR3603	Oak (Railway)	Safety Inspection	Bridge
BB0820Moor CourtGeneral InspectionBridgeBB0243Millbrook StreetGeneral InspectionBridgeBB0449Englands GateGeneral InspectionBridgeBB0216FloodgatesGeneral InspectionBridgeBB0064EyecoteGeneral InspectionBridgeBB0065LadymeadowGeneral InspectionBridgeBB0494Lugwardine Flats Flood Arch No.1Principal InspectionBridgeBB0494Lugwardine Flats Flood Arch No.9Principal InspectionBridgeBB0217SunsetGeneral InspectionBridgeBB0389BurningtonPrincipal InspectionBridgeBB0389BurringtonPrincipal InspectionBridgeBB0548Kingsland MillGeneral InspectionBridgeBB0300StreffordburyGeneral InspectionBridgeBB0303StreffordburyGeneral InspectionBridgeBB0304Kingsland MillGeneral InspectionBridgeBB0305Gipsy HallGeneral InspectionBridgeBB0306Marsh CrossingPrincipal InspectionBridgeBB0315Lugg Mills Flood Arch No.4General InspectionBridgeBB0325Lugg Mills Flood Arch No.4General InspectionBridgeBB0399JayGeneral InspectionBridgeBB0399JayGeneral InspectionBridgeBB0399JayGeneral InspectionBridgeBB0399JayGeneral InspectionBridge<	BB0801	Ridgeway Canal	General Inspection	Bridge
BB0243Millbrook StreetGeneral InspectionBridgeBB0449Englands GateGeneral InspectionBridgeBB0216FloodgatesGeneral InspectionBridgeBB0064EyecoteGeneral InspectionBridgeBB0486Lugwardine Flats Flood Arch No.1Principal InspectionBridgeBB0494Lugwardine Flats Flood Arch No.9Principal InspectionBridgeBB0531AltonGeneral InspectionBridgeBB0217SunsetGeneral InspectionBridgeBB0389BurringtonPrincipal InspectionBridgeBB0389BurringtonPrincipal InspectionBridgeBB0389SurringtonPrincipal InspectionBridgeBB0380StreffordburyGeneral InspectionBridgeBB0205Gipsy HallGeneral InspectionBridgeBB0300StreffordburyGeneral InspectionBridgeBB0316Marsh CrossingPrincipal InspectionBridgeBB0320StreffordburyGeneral InspectionBridgeBB0310Marsh CrossingPrincipal InspectionBridgeBB0320BrefordburyGeneral InspectionBridgeBB0321Paunton MillGeneral InspectionBridgeBB032Paunton MillGeneral InspectionBridgeBB0330StreffordburyGeneral InspectionBridgeBB0330BrefordburyGeneral InspectionBridgeBB0390JayGeneral InspectionBridgeBB	BB0280			Bridge
BB0449Englands GateGeneral InspectionBridgeBB0216FloodgatesGeneral InspectionBridgeBB0064EyecoteGeneral InspectionBridgeBB0486Lugwardine Flats Flood Arch No.1Principal InspectionBridgeBB0455LadymeadowGeneral InspectionBridgeBB0531AltonGeneral InspectionBridgeBB0217SunsetGeneral InspectionBridgeBB0389BurringtonPrincipal InspectionBridgeBB0389BurringtonPrincipal InspectionBridgeBB06531College Rd RailwaySafety InspectionBridgeBB0389BurringtonPrincipal InspectionBridgeBB06548Kingsland MillGeneral InspectionBridgeBB0205Gipsy HallGeneral InspectionBridgeBB0300StreffordburyGeneral InspectionBridgeBB016Marsh CrossingPrincipal InspectionBridgeBB0255Lugg Mills Flood Arch No.4General InspectionBridgeBB0319JayGeneral InspectionBridgeBB0462Wergin's South Flood Arch No.6General InspectionBridgeBB0555Lugg Mills Flood Arch No.6General InspectionBridgeBB0662Wergin's South Flood Arch No.6General InspectionBridgeBB0655ButterleyGeneral InspectionBridgeBB0655ButterleyGeneral InspectionBridgeBB0605ButterleyGeneral Inspection <td>BB0820</td> <td>Moor Court</td> <td>General Inspection</td> <td>Bridge</td>	BB0820	Moor Court	General Inspection	Bridge
BB0216FloodgatesGeneral InspectionBridgeBB0064EyecoteGeneral InspectionBridgeBB0486Lugwardine Flats Flood Arch No.1Principal InspectionBridgeBB0065LadymeadowGeneral InspectionBridgeBB0494Lugwardine Flats Flood Arch No.9Principal InspectionBridgeBB0531AltonGeneral InspectionBridgeBB0217SunsetGeneral InspectionBridgeBB0389BurringtonPrincipal InspectionBridgeBB0548Kingsland MillGeneral InspectionBridgeBB0205Gipsy HallGeneral InspectionBridgeBB0300StreffordburyGeneral InspectionBridgeBB016Marsh CrossingPrincipal InspectionBridgeBB0255Lugg Mills Flood Arch No.4General InspectionBridgeBB0399JayGeneral InspectionBridgeBB016Marsh CrossingPrincipal InspectionBridgeBB0555Lugg Mills Flood Arch No.4General InspectionBridgeBB0662Wergin's South Flood Arch No.6General InspectionBridgeBB0655ButterleyGeneral InspectionBridgeBB0655ButterleyGeneral InspectionBridgeBB0655ButterleyGeneral InspectionBridgeBB0655ButterleyGeneral InspectionBridgeBB0655ButterleyGeneral InspectionBridgeBB0605ButterleyGeneral InspectionBridg	BB0243	Millbrook Street	General Inspection	Bridge
BB0064EyecoteGeneral InspectionBridgeBB0486Lugwardine Flats Flood Arch No.1Principal InspectionBridgeBB0065LadymeadowGeneral InspectionBridgeBB0494Lugwardine Flats Flood Arch No.9Principal InspectionBridgeBB0531AltonGeneral InspectionBridgeBB0217SunsetGeneral InspectionBridgeBB0389BurringtonPrincipal InspectionBridgeBB0548Kingsland MillGeneral InspectionBridgeBB0205Gipsy HallGeneral InspectionBridgeBB0300StreffordburyGeneral InspectionBridgeBB03016Marsh CrossingPrincipal InspectionBridgeBB1232Paunton MillGeneral InspectionBridgeBB0555Lugg Mills Flood Arch No.4General InspectionBridgeBB0399JayGeneral InspectionBridgeBB0555Lugg Mills Flood Arch No.6General InspectionBridgeBB0662Wergin's South Flood Arch No.6General InspectionBridgeBB0655ButterleyGeneral InspectionBridgeBB0655ButterleyGeneral InspectionBridgeBB0655ButterleyGeneral InspectionBridgeBB0655ButterleyGeneral InspectionBridgeBB0655ButterleyGeneral InspectionBridgeBB0655ButterleyGeneral InspectionBridgeBB0655ButterleyGeneral InspectionBridge<	BB0449	Englands Gate	General Inspection	Bridge
BB0486Lugwardine Flats Flood Arch No.1Principal InspectionBridgeBB0065LadymeadowGeneral InspectionBridgeBB0494Lugwardine Flats Flood Arch No.9Principal InspectionBridgeBB0531AltonGeneral InspectionBridgeBB0217SunsetGeneral InspectionBridgeBB0970Maidenhyde FarmGeneral InspectionBridgeBB0389BurringtonPrincipal InspectionBridgeBB0548Kingsland MillGeneral InspectionBridgeBB0205Gipsy HallGeneral InspectionBridgeBB0300StreffordburyGeneral InspectionBridgeBB0316Marsh CrossingPrincipal InspectionBridgeBB0355Lugg Mills Flood Arch No.4General InspectionBridgeBB0399JayGeneral InspectionBridgeBB0662Wergin's South Flood Arch No.6General InspectionBridgeBB0605ButterleyGeneral InspectionBridgeBB0605ButterleyGeneral InspectionBridgeBB0605ButterleyGeneral InspectionBridgeBB0400Lugwardine Flats Flood Arch No.5Principal InspectionBridgeBB0490Lugwardine Flats Flood Arch No.5Principal InspectionBridgeBB0490Lugwardine Flats Flood Arch No.5Principal InspectionBridge	BB0216	Floodgates	General Inspection	Bridge
BB0065LadymeadowGeneral InspectionBridgeBB0494Lugwardine Flats Flood Arch No.9Principal InspectionBridgeBB0531AltonGeneral InspectionBridgeBB0217SunsetGeneral InspectionBridgeBB0970Maidenhyde FarmGeneral InspectionBridgeBB0389BurringtonPrincipal InspectionBridgeBB0548Kingsland MillGeneral InspectionBridgeBB0503College Rd RailwaySafety InspectionBridgeBB0205Gipsy HallGeneral InspectionBridgeBB0300StreffordburyGeneral InspectionBridgeBB0016Marsh CrossingPrincipal InspectionBridgeBB0555Lugg Mills Flood Arch No.4General InspectionBridgeBB0662Wergin's South Flood Arch No.6General InspectionBridgeBB0605ButterleyGeneral InspectionBridgeBB0605ButterleyGeneral InspectionBridgeBB0490Lugwardine Flats Flood Arch No.5Principal InspectionBridge	BB0064	Eyecote	General Inspection	Bridge
BB0494Lugwardine Flats Flood Arch No.9Principal InspectionBridgeBB0531AltonGeneral InspectionBridgeBB0217SunsetGeneral InspectionBridgeBB0970Maidenhyde FarmGeneral InspectionBridgeBB0389BurringtonPrincipal InspectionBridgeBB0548Kingsland MillGeneral InspectionBridgeBB0205Gipsy HallGeneral InspectionBridgeBB0300StreffordburyGeneral InspectionBridgeBB016Marsh CrossingPrincipal InspectionBridgeBB1232Paunton MillGeneral InspectionBridgeBB0399JayGeneral InspectionBridgeBB0309StreffordburyGeneral InspectionBridgeBB016Marsh CrossingPrincipal InspectionBridgeBB0399JayGeneral InspectionBridgeBB0399JayGeneral InspectionBridgeBB0662Wergin's South Flood Arch No.6General InspectionBridgeBB0605ButterleyGeneral InspectionBridgeBB0605ButterleyGeneral InspectionBridgeBB0462Orleton Railway(Wooferton, Tunnel Lane)Safety InspectionBridgeBB0490Lugwardine Flats Flood Arch No.5Principal InspectionBridge	BB0486	Lugwardine Flats Flood Arch No.1	Principal Inspection	Bridge
BB0531AltonGeneral InspectionBridgeBB0217SunsetGeneral InspectionBridgeBB0970Maidenhyde FarmGeneral InspectionBridgeBB0389BurringtonPrincipal InspectionBridgeBB0548Kingsland MillGeneral InspectionBridgeBR063College Rd RailwaySafety InspectionBridgeBB0930StreffordburyGeneral InspectionBridgeBR016Marsh CrossingPrincipal InspectionBridgeBB0255Lugg Mills Flood Arch No.4General InspectionBridgeBB0399JayGeneral InspectionBridgeBB0555Lugg Mills Flood Arch No.6General InspectionBridgeBB0662Wergin's South Flood Arch No.6General InspectionBridgeBF7927Broken BankGeneral InspectionBridgeBB0605ButterleyGeneral InspectionBridgeBR5045Orleton Railway(Wooferton, Tunnel Lane)Safety InspectionBridgeBB0490Lugwardine Flats Flood Arch No.5Principal InspectionBridge	BB0065	Ladymeadow	General Inspection	Bridge
BB0217SunsetGeneral InspectionBridgeBB0970Maidenhyde FarmGeneral InspectionBridgeBB0389BurringtonPrincipal InspectionBridgeBB0548Kingsland MillGeneral InspectionBridgeBR5063College Rd RailwaySafety InspectionBridgeBB0205Gipsy HallGeneral InspectionBridgeBB0930StreffordburyGeneral InspectionBridgeBR3607Yearsett RailwaySafety InspectionBridgeBB016Marsh CrossingPrincipal InspectionBridgeBB0355Lugg Mills Flood Arch No.4General InspectionBridgeBB0662Wergin's South Flood Arch No.6General InspectionBridgeBF7927Broken BankGeneral InspectionBridgeBB0605ButterleyGeneral InspectionBridgeBR5045Orleton Railway(Wooferton, Tunnel Lane)Safety InspectionBridgeBB0490Lugwardine Flats Flood Arch No.5Principal InspectionBridge	BB0494	Lugwardine Flats Flood Arch No.9	Principal Inspection	Bridge
BB0970Maidenhyde FarmGeneral InspectionBridgeBB0389BurringtonPrincipal InspectionBridgeBB0548Kingsland MillGeneral InspectionBridgeBR5063College Rd RailwaySafety InspectionBridgeBB0205Gipsy HallGeneral InspectionBridgeBB0930StreffordburyGeneral InspectionBridgeBR3607Yearsett RailwaySafety InspectionBridgeBB016Marsh CrossingPrincipal InspectionBridgeBB0555Lugg Mills Flood Arch No.4General InspectionBridgeBB0662Wergin's South Flood Arch No.6General InspectionBridgeBF7927Broken BankGeneral InspectionBridgeBB0605ButterleyGeneral InspectionBridgeBR5045Orleton Railway(Wooferton, Tunnel Lane)Safety InspectionBridgeBB0490Lugwardine Flats Flood Arch No.5Principal InspectionBridge	BB0531	Alton	General Inspection	Bridge
BB0389BurringtonPrincipal InspectionBridgeBB0548Kingsland MillGeneral InspectionBridgeBR5063College Rd RailwaySafety InspectionBridgeBB0205Gipsy HallGeneral InspectionBridgeBB0930StreffordburyGeneral InspectionBridgeBR3607Yearsett RailwaySafety InspectionBridgeBB0016Marsh CrossingPrincipal InspectionBridgeBB1232Paunton MillGeneral InspectionBridgeBB0399JayGeneral InspectionBridgeBB0662Wergin's South Flood Arch No.6General InspectionBridgeBF7927Broken BankGeneral InspectionBridgeBB0605ButterleyGeneral InspectionBridgeBR5045Orleton Railway(Wooferton, Tunnel Lane)Safety InspectionBridgeBB0490Lugwardine Flats Flood Arch No.5Principal InspectionBridge	BB0217	Sunset	General Inspection	Bridge
BB0548Kingsland MillGeneral InspectionBridgeBR5063College Rd RailwaySafety InspectionBridgeBB0205Gipsy HallGeneral InspectionBridgeBB0930StreffordburyGeneral InspectionBridgeBR3607Yearsett RailwaySafety InspectionBridgeBB0016Marsh CrossingPrincipal InspectionBridgeBB1232Paunton MillGeneral InspectionBridgeBB0555Lugg Mills Flood Arch No.4General InspectionBridgeBB0662Wergin's South Flood Arch No.6General InspectionBridgeBF7927Broken BankGeneral InspectionBridgeBB0605ButterleyGeneral InspectionBridgeBR5045Orleton Railway(Wooferton, Tunnel Lane)Safety InspectionBridgeBB0490Lugwardine Flats Flood Arch No.5Principal InspectionBridge	BB0970	Maidenhyde Farm	General Inspection	Bridge
BR5063College Rd RailwaySafety InspectionBridgeBB0205Gipsy HallGeneral InspectionBridgeBB0930StreffordburyGeneral InspectionBridgeBR3607Yearsett RailwaySafety InspectionBridgeBB0016Marsh CrossingPrincipal InspectionBridgeBB1232Paunton MillGeneral InspectionBridgeBB0555Lugg Mills Flood Arch No.4General InspectionBridgeBB0662Wergin's South Flood Arch No.6General InspectionBridgeBF7927Broken BankGeneral InspectionBridgeBB0605ButterleyGeneral InspectionBridgeBR5045Orleton Railway(Wooferton, Tunnel Lane)Safety InspectionBridgeBB0490Lugwardine Flats Flood Arch No.5Principal InspectionBridge	BB0389	Burrington	Principal Inspection	Bridge
BB0205Gipsy HallGeneral InspectionBridgeBB0930StreffordburyGeneral InspectionBridgeBR3607Yearsett RailwaySafety InspectionBridgeBB0016Marsh CrossingPrincipal InspectionBridgeBB1232Paunton MillGeneral InspectionBridgeBB0555Lugg Mills Flood Arch No.4General InspectionBridgeBB0399JayGeneral InspectionBridgeBB0662Wergin's South Flood Arch No.6General InspectionBridgeBF7927Broken BankGeneral InspectionBridgeBB0605ButterleyGeneral InspectionBridgeBR5045Orleton Railway(Wooferton, Tunnel Lane)Safety InspectionBridgeBB0490Lugwardine Flats Flood Arch No.5Principal InspectionBridge	BB0548	Kingsland Mill	General Inspection	Bridge
BB0930StreffordburyGeneral InspectionBridgeBR3607Yearsett RailwaySafety InspectionBridgeBB0016Marsh CrossingPrincipal InspectionBridgeBB1232Paunton MillGeneral InspectionBridgeBB0555Lugg Mills Flood Arch No.4General InspectionBridgeBB0399JayGeneral InspectionBridgeBB0662Wergin's South Flood Arch No.6General InspectionBridgeBF7927Broken BankGeneral InspectionBridgeBB0605ButterleyGeneral InspectionBridgeBR5045Orleton Railway(Wooferton, Tunnel Lane)Safety InspectionBridgeBB0490Lugwardine Flats Flood Arch No.5Principal InspectionBridge	BR5063	College Rd Railway	Safety Inspection	Bridge
BR3607Yearsett RailwaySafety InspectionBridgeBB0016Marsh CrossingPrincipal InspectionBridgeBB1232Paunton MillGeneral InspectionBridgeBB0555Lugg Mills Flood Arch No.4General InspectionBridgeBB0399JayGeneral InspectionBridgeBB0662Wergin's South Flood Arch No.6General InspectionBridgeBF7927Broken BankGeneral InspectionBridgeBB0605ButterleyGeneral InspectionBridgeBR5045Orleton Railway(Wooferton, Tunnel Lane)Safety InspectionBridgeBB0490Lugwardine Flats Flood Arch No.5Principal InspectionBridge	BB0205	Gipsy Hall	General Inspection	Bridge
BB0016Marsh CrossingPrincipal InspectionBridgeBB1232Paunton MillGeneral InspectionBridgeBB0555Lugg Mills Flood Arch No.4General InspectionBridgeBB0399JayGeneral InspectionBridgeBB0662Wergin's South Flood Arch No.6General InspectionBridgeBF7927Broken BankGeneral InspectionBridgeBB0605ButterleyGeneral InspectionBridgeBR5045Orleton Railway(Wooferton, Tunnel Lane)Safety InspectionBridgeBB0490Lugwardine Flats Flood Arch No.5Principal InspectionBridge	BB0930	Streffordbury	General Inspection	Bridge
BB1232Paunton MillGeneral InspectionBridgeBB0555Lugg Mills Flood Arch No.4General InspectionBridgeBB0399JayGeneral InspectionBridgeBB0662Wergin's South Flood Arch No.6General InspectionBridgeBF7927Broken BankGeneral InspectionBridgeBB0605ButterleyGeneral InspectionBridgeBR5045Orleton Railway(Wooferton, Tunnel Lane)Safety InspectionBridgeBB0490Lugwardine Flats Flood Arch No.5Principal InspectionBridge	BR3607	Yearsett Railway	Safety Inspection	Bridge
BB0555Lugg Mills Flood Arch No.4General InspectionBridgeBB0399JayGeneral InspectionBridgeBB0662Wergin's South Flood Arch No.6General InspectionBridgeBF7927Broken BankGeneral InspectionBridgeBB0605ButterleyGeneral InspectionBridgeBR5045Orleton Railway(Wooferton, Tunnel Lane)Safety InspectionBridgeBB0490Lugwardine Flats Flood Arch No.5Principal InspectionBridge	BB0016	Marsh Crossing	Principal Inspection	Bridge
BB0399JayGeneral InspectionBridgeBB0662Wergin's South Flood Arch No.6General InspectionBridgeBF7927Broken BankGeneral InspectionBridgeBB0605ButterleyGeneral InspectionBridgeBR5045Orleton Railway(Wooferton, Tunnel Lane)Safety InspectionBridgeBB0490Lugwardine Flats Flood Arch No.5Principal InspectionBridge	BB1232	Paunton Mill	General Inspection	Bridge
BB0662Wergin's South Flood Arch No.6General InspectionBridgeBF7927Broken BankGeneral InspectionBridgeBB0605ButterleyGeneral InspectionBridgeBR5045Orleton Railway(Wooferton, Tunnel Lane)Safety InspectionBridgeBB0490Lugwardine Flats Flood Arch No.5Principal InspectionBridge	BB0555	Lugg Mills Flood Arch No.4	General Inspection	Bridge
BF7927Broken BankGeneral InspectionBridgeBB0605ButterleyGeneral InspectionBridgeBR5045Orleton Railway(Wooferton, Tunnel Lane)Safety InspectionBridgeBB0490Lugwardine Flats Flood Arch No.5Principal InspectionBridge	BB0399	Jay	General Inspection	Bridge
BB0605ButterleyGeneral InspectionBridgeBR5045Orleton Railway(Wooferton, Tunnel Lane)Safety InspectionBridgeBB0490Lugwardine Flats Flood Arch No.5Principal InspectionBridge	BB0662	Wergin's South Flood Arch No.6	General Inspection	Bridge
BB0605ButterleyGeneral InspectionBridgeBR5045Orleton Railway(Wooferton, Tunnel Lane)Safety InspectionBridgeBB0490Lugwardine Flats Flood Arch No.5Principal InspectionBridge	BF7927		· · · · ·	-
BR5045Lane)Safety InspectionBridgeBB0490Lugwardine Flats Flood Arch No.5Principal InspectionBridge	BB0605	Butterley	General Inspection	-
BB0490 Lugwardine Flats Flood Arch No.5 Principal Inspection Bridge	BR5045	Orleton Railway(Wooferton, Tunnel	Safety Inspection	
BB0829 Leinthall Earles General Inspection Bridge	BB0490		Principal Inspection	Bridge
	BB0829	Leinthall Earles	General Inspection	Bridge

REFERENCE	NAME	INSPECTION TYPE	ASSET TYPE
BB0066	Richards Castle	Principal Inspection	Bridge
BB0618	Lugg Mills Flood Arch No.3	General Inspection	Bridge
BB0483	Humber	General Inspection	Bridge
BB0012	Lugg Mills	Principal Inspection	Bridge
BB0237	Staunton	General Inspection	Bridge
BB0817	Newtown	General Inspection	Bridge
BB0532	Broadhurst	General Inspection	Bridge
BF7915	Gig	General Inspection	Bridge
BB0724	Steen's Culvert	General Inspection	Bridge
BB0146	Dairy House	General Inspection	Bridge
BB0060	Broadward Flood Arch	Principal Inspection	Bridge
BB0493	Lugwardine Flats Flood Arch No.7	Principal Inspection	Bridge
BB0061	Marsh	General Inspection	Bridge
BR5061	Old School Lane Railway	Safety Inspection	Bridge
BB0393	Letton	General Inspection	Bridge
BF7772	Ivington Court	General Inspection	Bridge
BB0800	Fieldhouse Culvert	General Inspection	Bridge
BB0822	Luntley	General Inspection	Bridge
BB0055	Stockton	General Inspection	Bridge
BB0925	Duffield Farm	General Inspection	Bridge
BB0595	Hergest Flood Arch	General Inspection	Bridge
BR5076	Dinmore Station Railway	Safety Inspection	Bridge
BR5048	Docklow Railway	Safety Inspection	Bridge
BB0814	Newtown Culvert	Principal Inspection	Bridge
BB0489	Lugwardine Flats Flood Arch No.4	Principal Inspection	Bridge
BB0221	Weston	General Inspection	Bridge
BB0035	River Arrow Flood Culvert	General Inspection	Bridge
BB0564	Stagbatch Culvert	General Inspection	Bridge
BB0392	Lake	General Inspection	Bridge
BB0573	Ford Street Bridge	General Inspection	Bridge
BB0928	Rosedale	General Inspection	Bridge
BB0821	Lower Green Culvert	General Inspection	Bridge
BB0632	Gritpit	Principal Inspection	Bridge
BB0157	Venmore	General Inspection	Bridge
BB0377	Walford No.2	General Inspection	Bridge
BB0923	Avenbury	Principal Inspection	Bridge
BB0004	Lower Floodgates	General Inspection	Bridge
BB0610	Brierley	Principal Inspection	Bridge
BB0225	Bullocks Mill Flood Arch	General Inspection	Bridge
BB0620	Lugg Mills Flood Arch No.9 EA Blocked Up	General Inspection	Bridge
BB0385	Lingen	General Inspection	Bridge

REFERENCE	NAME	INSPECTION TYPE	ASSET TYPE
BB0514	Brockmanton	General Inspection	Bridge
BB0189	Yarpole Farm	Principal Inspection	Bridge
BB1053	Wilden's Cotts	General Inspection	Bridge
BB1055	Ivington Green	General Inspection	Bridge
BB2713	Manor House	Safety Inspection	Bridge
BB0452	Sutton Marsh	General Inspection	Bridge
BB0208	Hergest	General Inspection	Bridge
BB0919	Upton	Principal Inspection	Bridge
BB0378	Allcocks	General Inspection	Bridge
BF7910	Forest Wood	General Inspection	Bridge
BB0856	New House	General Inspection	Bridge
BB0804	Rhea	General Inspection	Bridge
BB0832	Comberton	General Inspection	Bridge
BF7933	Mahollam Farm	General Inspection	Bridge
BF7761	Little Frome	General Inspection	Bridge
BB0083	Brook	General Inspection	Bridge
BB0474	Eaton Culvert (Filled in)	Safety Inspection	Bridge
BB2003	Cadmore	Safety Inspection	Bridge
BB2010	Collington (Moiety) Worcs Bridge	Safety Inspection	Bridge
BW7231	Railway Cottage	Safety Inspection	Retaining Wall
BW7244	Stansbatch	Safety Inspection	Retaining Wall
BP7777	Sutton Rhea (BCI NOT Required, Occasional Inspection)	Safety Inspection	Bridge
BB1332	City Link Road Culvert (Formerly known as Police Training Ground Culvert)	General Inspection	Bridge
BB0434	Kinsham Culvert	Safety Inspection	Bridge
BB0842	Lugg Green Culvert (filled in)	Safety Inspection	Bridge
BB1021	Lugg Green Flood Arch No.2 (filled in)	Safety Inspection	Bridge
BB1020	Lugg Green Flood Arch No.1 (Filled in)	Safety Inspection	Bridge
BW7181	Yatton, Wigmore	Safety Inspection	Retaining Wall
BB0674	Wergin's Flood Arch No.7 (Filled in)	Safety Inspection	Bridge
BB1094	Biddulph Arms No.2	Safety Inspection	Bridge
BR5044	Berrington Railway	Safety Inspection	Bridge
BF7917	Bodenham	Safety Inspection	Bridge
BF7804	Sellack	Safety Inspection	Bridge
BF7803	Foy Suspension	Safety Inspection	Bridge
BR1276	Fencote Abbey (Safety Inspection Only)	Safety Inspection	Bridge
BP1273	Yatton Court Est	Safety Inspection	Bridge
BB0691	Old Furnace	Safety Inspection	Bridge
BW7245	Almeley	Safety Inspection	Retaining Wall
BW7015	Lyonshall	Safety Inspection	Retaining Wall

REFERENCE	NAME	INSPECTION TYPE	ASSET TYPE
BW7247	Lyonshall Station	Safety Inspection	Retaining Wall
BW7243	Titley Road	Safety Inspection	Retaining Wall
BW7246	Jays Cottage	Safety Inspection	Retaining Wall
BW7242	Broad Road	Safety Inspection	Retaining Wall
BB0164	Stone	Safety Inspection	Bridge
BF7911	Mousenatch	Safety Inspection	Bridge
BP1074	Russian Cottage	Safety Inspection	Bridge
BF7939	Saffrons Cross Footbridge	General Inspection	Bridge
BB5051	Bromyard Station Railway (also BR5051)	General Inspection	Bridge
BB0186	College Road Canal Bridge	Safety Inspection	Bridge
BB0039	Netherwood Culvert	Safety Inspection	Bridge
BP7940	Wicton Farm Disused Railway	Safety Inspection	Bridge
BP1312	Swiss Cottage Culvert	Safety Inspection	Bridge
BP1254	Stoke Bridge	Safety Inspection	Bridge
BP1265	Cheaton Brook	Safety Inspection	Bridge
BP1278	Pye Coppice	Safety Inspection	Bridge
BB1321	Lugwardine North Flood Arch No.2	Principal Inspection	Bridge
BR3608	Shelwick Green Railway	Safety Inspection	Bridge
BP 5125	Merton Meadow Car Park	Safety Inspection	Bridge
BP5066	Whitney Toll	Safety Inspection	Bridge
BP 7925	Wheelbarrow Castle	Safety Inspection	Bridge
BR5002	Withington Station Railway	Safety Inspection	Bridge
BR5039	Hunton Railway	Safety Inspection	Bridge
BP7938	Eaton Hall	Safety Inspection	Bridge
BB0228	Lower Harpton	Safety Inspection	Bridge
BP1268	Prospect Cottage	Safety Inspection	Bridge
BP1272	Church F/Br	Safety Inspection	Bridge
BF7917	Bodenham	Safety Inspection	Bridge
BF7804	Sellack	Safety Inspection	Bridge
BB0691	Old Furnace	Safety Inspection	Bridge
BB0164	Stone	Safety Inspection	Bridge
BP1074	Russian Cottage	Safety Inspection	Bridge
BF7911	Mousenatch	Safety Inspection	Bridge
BW7294	Perrywood Retaining Wall Wigmore	Safety Inspection	Retaining Wall
BW7293	Stanway Bungalow Retaining Wall	Safety Inspection	Retaining Wall
BR5070	Malvern Tunnel B	Safety Inspection	Bridge
BW7278	Pontrilas B4347 Retaining Wall	General Inspection	Retaining Wall
BF7917	Bodenham	Safety Inspection	Bridge
BF7804	Sellack	Safety Inspection	Bridge
BF7803	Foy Suspension	Safety Inspection	Bridge
BB0039	Netherwood Culvert	Safety Inspection	Bridge

REFERENCE	NAME	INSPECTION TYPE	ASSET TYPE
BB0691	Old Furnace	Safety Inspection	Bridge
BB1094	Biddulph Arms No.2	Safety Inspection	Bridge
BB0164	Stone	Safety Inspection	Bridge
BP1074	Russian Cottage	Safety Inspection	Bridge
BF7911	Mousenatch	Safety Inspection	Bridge
BS9130	Sainsburys Hereford (UCB Only - Safety Inspection)	Safety Inspection	Barrier

Specialist Inspections

Safety Barriers

REFERENCE	NAME	INSPECTION TYPE
BS9060	Woodredding Farm Section 2	Safety Barrier Inspection
BS9003	Poplar Cottage	Safety Barrier Inspection
BS9134	A465 City Link Road Section 1	Safety Barrier Inspection
BS9171	Kinsham Bridge Barrier NE	Safety Barrier Inspection
BS9175	Parsons Pole Bridge Barrier NW	Safety Barrier Inspection
BS9172	Kinsham Bridge Barrier SE	Safety Barrier Inspection
BS9173	Parsons Pole Bridge Barrier SE	Safety Barrier Inspection
BS9093	A44 Bromyard	Safety Barrier Inspection
BS9174	Parsons Pole Bridge Barrier SW	Safety Barrier Inspection
BS9011	Woodredding Cottage	Safety Barrier Inspection
BS9088	Bromyard Tensbury Road	Safety Barrier Inspection
BS9039	C1196 Junction	Safety Barrier Inspection
BS9001	Marlbrook Cadbury's Section SE	Safety Barrier Inspection
BS9081	Rowden Abbey	Safety Barrier Inspection
BS9169	Kinsham Bridge Barrier SW	Safety Barrier Inspection
BS9061	Woodredding Farm Section 3	Safety Barrier Inspection
BS9076	Stanford Bishop, Boyce Caravan Park East	Safety Barrier Inspection
BS9135	A465 City Link Road Section 2	Safety Barrier Inspection
BS9072	Aston Crews jct. of C1281	Safety Barrier Inspection
BS9170	Kinsham Bridge Barrier NW	Safety Barrier Inspection
BS9176	Parsons Pole Bridge Barrier NE	Safety Barrier Inspection
BS9168	Buckton Bridge Barrier NW	Safety Barrier Inspection
BS9167	Buckton Bridge Barrier SW	Safety Barrier Inspection
BS9165	Buckton Bridge Barrier NE	Safety Barrier Inspection
BS9165	Buckton Bridge Barrier SE	Safety Barrier Inspection
BS9099	Rhydspence Inn South	Safety Barrier Inspection
BS9028	Dilwyn Bypass	Safety Barrier Inspection
BS9028 BS9126	Red Brook Culvert S	Safety Barrier Inspection
039120		Salety Damer Inspection

REFERENCE	NAME	INSPECTION TYPE
BS9063	Bridge Sollers NE	Safety Barrier Inspection
BS9086	Morrisons Section 2	Safety Barrier Inspection
BS9022	Jays Green - NE	Safety Barrier Inspection
BS9127	Norton Brook Culvert S	Safety Barrier Inspection
BS9056	Wigmore	Safety Barrier Inspection
BS9015	Beggars Ash	Safety Barrier Inspection
	New Roman Rd, West of Pinston	
BS9066	House	Safety Barrier Inspection
BS9009	Cusop	Safety Barrier Inspection
BS9058	Bridge Sollers Bridge NW	Safety Barrier Inspection
BS9064	Bridge Sollers SE	Safety Barrier Inspection
BS9055	Morrisons Section 1	Safety Barrier Inspection
BS9065	Russian Cottage, North	Safety Barrier Inspection
BS9084	Marlbrook Section NE	Safety Barrier Inspection
BS9080	Rhydspence West	Safety Barrier Inspection
BS9068	Roman Rd East of the Bolts	Safety Barrier Inspection
BS9079	Hillpike	Safety Barrier Inspection
BS9014	Adforton Village	Safety Barrier Inspection
BS9069	Roman Rd East of U73007	Safety Barrier Inspection
BS9031	Clifford	Safety Barrier Inspection
BS9070	Roman Rd East of U73007 Section 2	Safety Barrier Inspection
BS9027	Monkland by River Bridge	Safety Barrier Inspection
BS9085	Marlbrook Section NW	Safety Barrier Inspection
BS9067	New Roman Rd, West of the Bolts	Safety Barrier Inspection
BS9045	Leominster Railway SW	Safety Barrier Inspection
BS9037	Russian Cottage, South	Safety Barrier Inspection
BS9103	Red Brook Culvert N	Safety Barrier Inspection
BS9052	Moreton-on-Lugg	Safety Barrier Inspection
BS9038	Bodenham	Safety Barrier Inspection
BS9046	Leominster Footbridge	Safety Barrier Inspection
BS9059	Bridge Sollers Bridge SW	Safety Barrier Inspection
BS9016	Knapp Lane	Safety Barrier Inspection
BS9006	Todding	Safety Barrier Inspection
BS9078	Leominster Railway Bridge SE	Safety Barrier Inspection
BS9053	Stretton Sugwas Village	Safety Barrier Inspection
BS9044	Leominster Railway NW	Safety Barrier Inspection
BS9094	Kington - Crooked Well	Safety Barrier Inspection
BS9083	Catson, East of Little Dewchurch	Safety Barrier Inspection
BS9024	Gorsley, By Primary School	Safety Barrier Inspection
	Stanford Bishop, Boyce Caravan Park	· · · · · · · · · · · · · · · · · · ·
BS9075	West	Safety Barrier Inspection
BS9035	Pinston House	Safety Barrier Inspection
BS9049	Dansford (Marlbrook)	Safety Barrier Inspection

REFERENCE NAME **INSPECTION TYPE** BS9020 Marlbrook Section SW Safety Barrier Inspection BS9077 Leominster Railway Bridge NE Safety Barrier Inspection BS9087 **Morrisons Section 3** Safety Barrier Inspection BS9005 **Rhydspence Inn North** Safety Barrier Inspection BS9095 Whitney Safety Barrier Inspection Junction with U90611 Brilley BS9018 Safety Barrier Inspection BS9032 Cusop (Nr Hay-on-Wye) Safety Barrier Inspection BS9017 Road to Brilley Safety Barrier Inspection BS9062 Cusop Hill Safety Barrier Inspection BS9090 Floodgates Safety Barrier Inspection **River Arrow W** BS9096 Safety Barrier Inspection BS9036 Back Brook NW Safety Barrier Inspection BS9115 **River Arrow E** Safety Barrier Inspection BS9113 Back Brook SE Safety Barrier Inspection BS9111 Safety Barrier Inspection Jays Green NW BS9004 **Rhydspence East** Safety Barrier Inspection BS9131 B4347 Kentchurch Safety Barrier Inspection Sainsburys Hereford (UCB Only -**BS9130** Safety Inspection) Safety Inspection BS9133 Garren Dale Road Safety Barrier Inspection **BS9144** A40 Hildersley Safety Barrier Inspection BS9030 Safety Barrier Inspection Gurneys Oak BS9104 Norton Brook Culvert N Safety Barrier Inspection BS9040 Burcott Rd Canal Side Safety Barrier Inspection Old Canal near Aylestone Rbt Section BS9071 2 Safety Barrier Inspection Old Canal near Aylestone Rbt Section **BS9054** Safety Barrier Inspection BS9050 **Outfall Works Road** Safety Barrier Inspection BS9129 Llangua Bridge Upstream End Safety Barrier Inspection BS9105 Locks Garage - Northern ADS Safety Barrier Inspection **River Wall South of Pontrilas BS9108** Safety Barrier Inspection BS9107 Wormbridge Bridge Upstream East Safety Barrier Inspection **BS9128** Wormbridge Bridge Downstream West Safety Barrier Inspection Pontrilas Builders Merchants BS9109 Safety Barrier Inspection BS9106 Locks Garage - Southern ADS Safety Barrier Inspection BS9110 Llangua Bridge Downstream End Safety Barrier Inspection BS9033 Barrack Hill Safety Barrier Inspection BS9051 **Ballingham Hill** Safety Barrier Inspection Westholme Road, Hereford Safety Barrier Inspection BS9073 A417 Ledbury Bypass Safety Barrier Inspection BS9091 BS9021 Eastnor Safety Barrier Inspection BS9057 Poolend Safety Barrier Inspection

Balfour Beatty Council Working for Herefordshire

REFERENCE	NAME	INSPECTION TYPE
BS9114	Little Marcle Road South	Safety Barrier Inspection

Diving Inspections:

REFERENCE	NAME	STRUCTURE TYPE
BB0245	Eardisley Culvert	Bridge
BF7874	Hampton Meadow	Bridge
BB0143	Eign Street Culvert (confined space)	Bridge
BB0098	Hampton Court	Bridge
BW7257	Kington Bridge Wall	Retaining Wall
BB0001	Mordiford	Bridge
BB0226	Plough Lane Culvert	Bridge
BB0117	Attwood Lane Culvert	Bridge
BB0189	Yarpole Farm	Bridge
BB0837	Yarpole	Bridge
BB1150	Mortimers Cross Culvert	Bridge
BB0012	Lugg Mills	Bridge
BB0718	Poswick	Bridge
BB0072	Little Hereford	Bridge
BB0630	Longlands	Bridge
BB0930	Streffordbury	Bridge
BB0017	Moreton-On-Lugg Bridge	Bridge
BB0209	Mahollam	Bridge
BB1188	Mill (Bullocks Mill)	Bridge
BB0276	Kings Meadow Culvert	Bridge
BB0229	Hunton Bridge	Bridge
BB0015	Wergins	Bridge
BB0111	Llangua (Moiety Monmouthshire)	Bridge
BB0306	New Mills	Bridge
BB0135	Morehampton	Bridge
BB0606	Moorend	Bridge
BW7097	River Wall, South of Pontrilas	Retaining Wall
BF7851	Victoria Footbridge	Bridge
BB0325	Wilton	Bridge
BB0513	Holme Lacy	Bridge
BB0623	Huntsham	Bridge
BB0170	Old Wye Bridge	Bridge
BW7179	Outfall Works, River Wall	Retaining Wall
BB5068	Hunderton River Bridge	Bridge
BB0759	Kerne	Bridge
BW7069	River Sheet Piles, Pontrilas	Retaining Wall
BB0056	Eaton	Bridge

REFERENCE	NAME	STRUCTURE TYPE
BB0101	Bodenham Bridge	Bridge
BB0424	Hampton Mill	Bridge
BB0390	Criftinford	Bridge
BB0161	Eardisland	Bridge
BB0389	Burrington	Bridge
BB0987	Trereece	Bridge
BB0202	Eardisley	Bridge
BB0140	Grosmont	Bridge
BB0006	Fiveways Culvert	Bridge
BB0185	Bredwardine	Bridge
BB0166	Commercial Road Culvert	Bridge
BB0624	Hoarwithy	Bridge
BB0010	Lugwardine Bridge	Bridge

APPENDIX C – LIST OF NOMINATED SUBCONTRACTORS

Refer to budget master for a detailed breakdown.

Service Order Title	Total £
Capital Major Schemes	£450,000.00
Capital Minor Schemes	£225,000.00
Enabling Works	£34,115.53
Principle Inspections	£212,944.11
Structures Diving Inspections & Maintenance	£32,154.16
Structures General Inspections Revenue	£42,702.75
Safety Barrier Inspections Revenue	£6,478.14
Structures General Inspections Captial	£42,702.75
Safety Barrier Inspections Capital	£6,478.14
Bridge Strike Support	£0.00
Planning/Adoption	£9,984.48
Development Control & Network Management	£14,865.80

APPENDIX D – LIST OF NOMINATED SUBCONTRACTORS

WSP – Design Consultant.

GW Marine – Structures diving inspections and maintenance.

Ibex – Roped Access Inspection.

Schemes would be delivered by sub-contractor once they have been out too tender and awarded through the Balfour Beatty procurement tender system Jaggaer.

Balfour Beatty Council Working for Herefordshire